Construction division. Advice for giving credit to contractors/suppliers.

Sl. No. – site bills register	12	96.		Date Regist		bill	s	01/11/	23.	
Company Name:	GVA	2 C		Site:				Innopolis		
Name of Contractor	7.	Esh	var	Lao						
Nature of work	, ,		ldin			110	_don Date	e.		
Work done	From D	ate '		V		То	Date			
SI. Villa/Flat/block n No. Scattolding	o. Qty		Rate		Unit	s	Amoun	t	Contractors bill no	
1. LR-3383 old re	marin 2,	47968	2.0	D	57	+	4,9	59.31.		
2. 12-3384 remov	ing 21	479.66	2-0	50	5-4	ナ	4,9	59-36		
3. LR-3383-1/201		4796	3.0	50	54	+	7,4	34.04		
4. LR-3384 tin	La 21	429.65	3-	00	SH	4	714	24,04		
5.	1	·								
6.										
7.										
8Add	- 10%	-181	Loar	rellin	9					
9.	19	om 1	- 0 0	0.00			2111	2a. [8		
10.			as p		1		1 7 01	7 1. 00		
11. To	otal:						27,	126		
Bill required	YES [□ NO.		GST	bill 1	equ			NO.	
Measurement &	Requir	red	-	Meas	suren	nent	&	Encl	losed	
estimate sheet:	☐ Not re			estin	ate s	hee	t:	□Not	enclosed	
PO/WO no.				PO/\	VO d	late:				
Remarks :										
				1.						
										
									4	
pproved by Project Man	Appro	ved b	y Des	ign]	Геал	m Ap	proved	l by M.D.		
ate:		Date:					Da	ate:	_ 1	
gn: Yullw		Sign:					Si	gn:		

Notes: 1. This advice must be sent within 7 days of completing work. 2. This form can be used for certifying labour bills, bills for hire charges, earth work, turnkey civil contractors. 3. Wherever not applicable – fill NA. 4. Estimate and measurement sheets are not required for turnkey jobs where guideline rates are clearly given.

		d	S		
_	A	ú			

DOTTMATE CHEE	т						
ESTIMATE SHEE							
Company Name:	GVRC				Appr	Madhu	
Project:	INNOPOLIS					Viau	
Work Description:	Scaffolding work done.		1	4-17 1 10	Sign:		
Contactor Name:	Eashwar rao				-		
Prepared By:	Madhan.O			- 300			
Date:	30.10.20223						
							Item Head Total
S No.	Item Head	Item Description	Quantity	Units	Rate	A moure	
1	Johnson lift shaft scaffolding removing work done at atrium.	LR-3383 old scaffolding removing	2,479.68	SFT	2.00	4,959.36 4,959.36	
2							
Z	Johnson lift scaffolding removing work done at atrium.	LR-3384 old scaffolding removing work done.	2,479.68	SFT	2.00	4,939.04	
3	Johnson lift scaffolding removing work done at atrium. Johnson lift shaft scaffolding work done at atrium.	LR-3384 old scaffolding removing work done. LR-3383 New scaffolding fixing work done.	2,479.68 2,479.68	SFT	2.00 3.00	7,439.04	
3 4						7,439.04 7,439.04	
3 4	Johnson lift shaft scaffolding work done at atrium.	LR-3383 New scaffolding fixing work done.	2,479.68	SFT	3.00	7,439.04 7,439.04 24,796.80	
3 4	Johnson lift shaft scaffolding work done at atrium.	LR-3383 New scaffolding fixing work done. LR-3384 New scaffolding fixing work done.	2,479.68	SFT	3.00	7,439.04 7,439.04 24,796.80 2,479.68	3
3 4	Johnson lift shaft scaffolding work done at atrium.	LR-3383 New scaffolding fixing work done.	2,479.68	SFT	3.00	7,439.04 7,439.04 24,796.80 2,479.68	3

SHEET							
GVRC						Madhu	
INNOPOLIS		++		Ap	proved by.		
Scaffolding work done.				Sig	n:		
Eashwar rao				-			
Madhan.O		-					
30.10.20223						BXCXD	F
		A	В	C	D	Quantity	Units
Item Head	Item Description	Length	Width	Height	Nos.		SFT
Johnson lift shaft scaffolding removing work done at atrium.	LR-3383 old scaffolding removing	8.00	1.00	88.56	2.00	1	SFT
	(scaffolding removing work done.)	6.00	1.00	88.56	2.00	2479.68	SFT
					Total		SFT
Johnson lift scaffolding removing work done at atrium.	LR-3384 old scaffolding removing work done.	8.00	1.00	88.56	2.00	\	SFT
	(scaffolding removing work done.)	6.00	1.00	88.56	2.00		SFT
	,					1416.96	SFT
Johnson lift shaft scaffolding work done at atrium.	LR-3383 New scaffolding fixing work done.	8.00	1.00	88.56			SFI
		6.00	1.00	88.56			SFT
	3 3						SFI
Johnson lift shaft scaffolding work done at atrium.	LR-3384 New scaffolding fixing work done.	8.00	_				
Annual war same same same		6.00	1.00	88.56		2179 65	1 077
					Total		
	Scaffolding work done. Eashwar rao Madhan.O 30.10.20223 Item Head Johnson lift shaft scaffolding removing work done at atrium. Johnson lift scaffolding removing work done at	Scaffolding work done. Eashwar rao Madhan.O 30.10.20223 Item Head Item Description LR-3383 old scaffolding removing work done at atrium. (scaffolding removing work done.) Johnson lift scaffolding removing work done at atrium. LR-3384 old scaffolding removing work done. (scaffolding removing work done.) Johnson lift shaft scaffolding work done at atrium. LR-3383 New scaffolding fixing work done. (scaffolding fixing work done.)	Scaffolding work done. Eashwar rao Madhan.O 30.10.20223 A Item Head Item Description Length Johnson lift shaft scaffolding removing work done at atrium. (scaffolding removing work done.) Johnson lift scaffolding removing work done at atrium. (scaffolding removing work done.) LR-3384 old scaffolding removing work done. (scaffolding removing work done.) Johnson lift shaft scaffolding work done at atrium. LR-3383 New scaffolding fixing work done. (scaffolding fixing work done.) Johnson lift shaft scaffolding work done at atrium. LR-3384 New scaffolding fixing work done. 8.00 Johnson lift shaft scaffolding work done at atrium. LR-3384 New scaffolding fixing work done. 8.00 Scaffolding fixing work done.	Scaffolding work done. Eashwar rao Madhan.O 30.10.20223 A B Item Head Item Description Length Width Johnson lift shaft scaffolding removing work done at atrium. (scaffolding removing work done.) LR-3383 old scaffolding removing work done. (scaffolding removing work done.) LR-3384 old scaffolding removing work done. LR-3384 old scaffolding removing work done. (scaffolding removing work done.) Johnson lift shaft scaffolding work done at atrium. LR-3383 New scaffolding fixing work done. Scaffolding fixing work done.	Scaffolding work done. Eashwar rao Madhan.O 30.10.20223 A B C Item Head Item Description Length Width Height Johnson lift shaft scaffolding removing work done at atrium. (scaffolding removing work done.) LR-3383 old scaffolding removing work done.) Johnson lift scaffolding removing work done at atrium. (scaffolding removing work done.) LR-3384 old scaffolding removing work done. (scaffolding removing work done.) LR-3384 old scaffolding removing work done. (scaffolding removing work done.) Johnson lift shaft scaffolding work done at atrium. LR-3383 New scaffolding fixing work done. (scaffolding fixing work done.) LR-3384 New scaffolding fixing work done. LR-3384 New scaffolding fixing work done. 8.00 1.00 88.56 (scaffolding fixing work done.) LR-3384 New scaffolding fixing work done. 8.00 1.00 88.56	Sign: Sign	Sign: Sign