Quality Control Check Repot. Stage: After Finishing Stage III (Apartments)

Proceed with further wor	Proceed with furth	Stop further work.	Recommendation:	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No
Proceed with further work. ATR not required.	Proceed with further work. Proceed with work after submitting ATK on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.			no.	K. Shirish Kuray Sign	T. vinod Kumay	PMR-I	6-115
iired.	ter submitting ATK on the confections pointed	eport to QC team. Proc		MD Sign	4.0888	Sign	Sign	Project	Other
	d out in the OC report.	eed only after recheck			Report filed and signed by PM	Exter	- Vina Kumas	PMR-I	-
-	ATR not required.	by QC.		For filling	ed by PM	Date	Date	Phase	SI. No.
				□Yes □No	Yes No	14/05/19	14/05/19	71.	.33590

Inspection should be done after:

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of '/' from the wall
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided
☐Yes ☑No		Good Avg Poor Modular kitchen gr	∠Yes □No
Video door phone provided	workman ship & finishing	Modular kitchen granite & dado	Modular kitchen provided
☐ Yes ☐ No		☐ Good ☑ Avg ☐ Poor	☑Yes □No