50	Quality Con
	Quality Control Check Repot.
	t.
	Stage: After Finishing Stage III (Apartme
	ning Stage III
	(Apartments)

Flat No C-	C-201	Other		Sl. No.	27809
Company BMC	C	Project	MFG	Phase	F)
Prepared by P. So.	P. Sal okumer	Sign	Prody	Date	16/8/17
Project Manager S.V. Subc	S.V. Suba Reddy Sign	Sign	V. Guarkungt	Date	41812
Previous stage report no.	,	27269	Report filed and signed by PM		YYes □No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	ATR on QC re with work aft nly after mak ATR not requ	port to QC team. Procler submitting ATR on ing corrections pointeired.	eed only after recheck I QC report to QC team d out in the QC report.	by QC. ATR not required.	

inspection should be done after:

- Completing stage II works.

  Complete works like windows, grills, electrical wiring, switches, french door glass, etc.

  In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

  1. Window grills must be fitted at the depth of ¼" from the wall.

  2. Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

	-		_	
Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided	MISCELIAITEOUS CHECK.
No □No		Good Navg Poor	Yes □No	
Video door phone provided	workman ship & finishing	Good Novg Poor Modular kitchen granite & dado	Modular kitchen provided	
Xes No		Good NAvg Poor	Nes □ No	•

Page 2 of 2