Recommendation: Checked By MD on Previous stage report no. Project Manager Flat No Prepared by Company Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Proceed with further work. ATR not required. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Subba Keddy M. Iga Sigher のとなっ Quality Control Check Repot. C-905 Other Sign Sign MD Sign Project 45448 Stage: After Finishing Stage III (Apartments) Report filed and signed by PM て広 4 1 Date For filling Date Phase Sl. No. Yes F1/80/80 08/08/17 Yes 9477B No No No

Completing stage II works.

Inspection should be done after:

- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

## Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

	Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided
	✓ Yes ☐ No		☐ Good ☐ Avg ☐ Poor   Modular kitchen grani	☐ Yes ☑ No
	Video door phone provided	workman ship & finishing	Modular kitchen granite & dado	Modular kitchen provided
1000	MYes □No		Good Avg Poor	Yes No