	Quality Control Check Repot.	İ	Stage: After Finishing Stage III (Apartments)	ge III (Apartments)	
Flat No	F-601	Other		SI. No.	30601
Company	BAC	Project	370	Phase	(2)
Prepared by					=
	C. Sura Lynna	Sign	1	Date	21/20/18
rroject Manager	Bubbon Re My Sign	Sign	10 "	Date	2.12/10
Previous stage report no.	no.	井中 R R R R R R R R R R R R R R R R R R R	Report filed and signed by Pl	ed by PM	Yes No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation:					
Stop further work.  Stop further work.  Proceed with furth  Proceed with furth	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR no Proceed with further work.	port to QC team. Proc ter submitting ATR on ing corrections pointed ired	ced only after recheck QC report to QC team d out in the QC report.	by QC. ATR not required.	

Inspection should be done after:

- Completing stage II works.

  Complete works like windows, grills, electrical wiring, switches, french door glass, etc.

  In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

## Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

video door phone to be provided .		Modular kitchen workman ship		Modular kitchen to be provided	
✓Yes ☐No	4:4	☐Good ☐Avg ☐ Poor		Yes No	
Video door phone provided	workman ship & finishing	Good Avg Poor Modular kitchen granite & dado		Modular kitchen provided	
☐ Yes ☐ No		Good Avg Poor	L too with	Type Who	