## Quality Control Check Repot. Stage: After Finishing Stage III (Apartments)

	Diat NI		> 1			
Project  Project  N. S. K. Sign  Sign  Ort no.  N. S. W. S. Mer. Reads  Sign  N. S. W. S. Meds  Sign  N. Sign  N. S. W. S. Meds  Sign  N. S. W. S. Meds  N. Sign  N. Sign  N. S. W. S. Meds  N. S. W. S. W. S. W. S. Meds  N. S. W. S. W. S. W. S. W. S. Meds  N. S. W.	Flat NO	B-103	Other		Sl. No.	22034 2024
Sign  Ort no.  Sign  Date  Ort no.  N. M. Report filed and signed by PM  MD Sign  MD Sign  Report filed and signed by PM  Report filed and signed by PM  Report filed and signed by PM  For filling  Report following ATR on QC report to QC team. Proceed only after recheck by QC.  Ork. Proceed with work after submitting ATR on QC report to QC team.	Company	BUC	Project	いかく		
ort no.  Sign  Crimo.  Crimo.	Prepared by		Sign	2016		22/2/19
ort no.  "2 7c3 Report filed and signed by PM  MD Sign  MD Sign  For filling  rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  ork. Proceed with work after submitting ATR on QC report to QC team.	Project Manager	S.V.Super Reddy	Sign	1 Disarbuny	Date	77/2/7
MD Sign  For filling  rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  ork. Proceed with work after submitting ATR on QC report to QC team.	Previous stage report	no.	22055	Report filed and signe	ed by PM	□YYes □No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making formations are interesting to the CC.	Checked By MD on		MD Sign		For filling	□Yes □No
Proceed with further work. ATR not required.	Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Submit ATR on QC re Proceed with work aft er work only after mak er work. ATR not requi	port to QC team. Proce er submitting ATR on ing corrections pointed ired.	eed only after recheck QC report to QC team I out in the QC report.	by QC. ATR not required.	

- Completing stage II works.
- Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

  1. Window grills must be fitted at the depth of '4" from the wall.

  2. Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

video door phone to be provided		Modular kitchen workman ship	
☐ Yes ☐ No		Good ☐ Avg ☐ Poor	☐ Yes ☐ No
Video door phone provided	workman ship & finishing	Good Avg Poor Modular kitchen granite & dado	Modular kitchen provided
Yes No		Good Avg Poor	☐Yes ☐No