1	
	uality
The second second second	Contro
	Duality Control Check Repot.
	e III
	III (Villas)

Flat No	·. 5	Other		Sl. No.	27100
Company	TAN	Project	Milpur hours	Phase)-1
Prepared by	P.S. S. Kimar	Sign	Porchy	Date	26/4/17
Project Manager	Kindowider Reddy Sign	Sign	(tracedo)	Date	26/4/17
Previous stage report no.).	135	Report filed and signed by PM	d by PM	√Yes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QU Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.	Stop further work. Submit ATR on QC report Stop further work. Proceed with work after some Proceed with further work only after making proceed with further work. ATR not required	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck l Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	y QC.	

- Completing stage II works.
- Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made,

Stage III check notes:

- Window grills must be fitted at the depth of 14" from the wall Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

	Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided	ATTACON CHO CHOCK
	☐Yes ☐No ←		Good Avg Poor	☑Yes □No	
the second secon	Video door phone provided	workman ship & finishing	☐ Good [Avg [] Poor Modular kitchen granite & dado	Modular kitchen provided	
	☐ Yes ☐ No —		Good Avg Poor	√Yes □No	

9

Lobby-l

Drawing Bedroom 3 Bedroom 2 Bedroom 1

93

S No

Room

covering with plastic

Junction box covers

covers

painting

Remarks

Other

Toilet 3 Toilet 2 Toilet 1 Kitchen

17

Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

$\overline{}$	 	_						
	Remarks:		Quality and workmanship of lawn	Cleaning/painting of external cladding/texture	Painting of gates & railings	Quality and workmanship of railings	Quality and workmanship of gate	Miscellaneous check — after finishing stage III
			Good Avg. Poor	Good VAvg. Poor	Good Avg. Poor	Good Avg. Poor	Good Avg. Poor	