## Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No. $C-303$ Other		Sl. No.	26988
Company Vista Homes Project	MUSTON HOMES	Phase	
Prepared by San Sign	.4)	Date	14/4/17
Project Manager T Machill Sign	The state of the s	Date	14/4/14.
Previous stage report no.	Report filed and signed by PM?		Yes No
Additions & alterations sheet date	All pages signed by engineer & customer?		∐Yes ∐No
Checked By MD on MD Sign		For filling	∏Yes ∏No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	ceed only after recheck? n QC report to QC team ed out in the QC report.	by QC. ATR not required.	

#### Inspection should be done alter:

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be filed.
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request

### After Plumbing & Electrical Check.

- Mark v for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- 11. In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

# Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

				Т .		Γ		Ι	_	1				Γ		_	г	_				
Revi	Sign	Rem			Rem	15	14	13	12	11	10	9	∞	7	6	5	4	3	2	<b>_</b>	S No	-
Revised drawing required from HO	Signed by engineer,	Remarks on additions & alteration sheet:			Remarks Tr M.Be	Other	Other	Kitchen	Utility/balcony-3-	Utility/balcony-2-	Utility / balcony 1	Lobby-1	Dining	Drawing	Toilet3	Bedroom-3	Toilet 2 C. Toi	Bedroom 2 R-Bed	Toilet 1 M. Toi.	Bedroom 1 M. Bed	Room	
om HO	T C	eration sheet:			M. Bed & M. To.			}	1	7	1	1	1	1		-	1	)	-	-	near pipes in balcony & utility ( • or ×)	Civil work
Yes No	Yes No		The control of the co	ì	Switch			ζ	1	ς.	1	-	1	1	1	1	ζ	1	7	1	PVC Check ( • or ×)	CPVC &
Approve	Signed b			**************************************	boood is			۲	1	(	ζ,	-	ζ	ς,	1	•	ς	ς	7	(	points check ( v or x)	Electrical
Approved revised drawing	Signed by customer,		- Andrews of the Control of the Cont		Prosectino			1	ļ	ζ	1	1	1	3		•	5	,	(	)	ng (v or	Water
ng attached	[T]				a and boss			1	•	ζ	1	1	1	}	ì			1	)		fasteners check ( or x)	Proper use of
]Yes □No	Yes No				吉			1	1		1	1	1	ζ	!	•	1	-		1	1000	Placement of
1					Sec.			)	)	١	)	)	)	<	)	)	)	,	}	}	Generator changeover ( v or x)	Placement of