Quality Control Check Repot. Stage: After Plastering (Apartments)

Flat No.	F-cc1	Other		SI. No.	4.5016
Company	BNC	Project	りょみ	Phase	<u> =</u>)
Prepared by	M. Tega Svidler	Sign	A	Date	41/40/61
Project Manager	Subba Reddy	Sign	rolal	Date	19/04/17.
Previous stage report no.	no.	26907	Report filed and signed by PM?	d by PM?	MYes □No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck less Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	port to QC team. Procter submitting ATR on ing corrections pointedired.	scommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	by QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed,
- before starting painting, tiling & flooring.

Plastering Check. Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be i" to 2" larger. (Tolerance: I")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct beight, at one level & without broken edges.

Rei	15	14	13	12	=	10	9	8	7	6	S	4	ω	2	-	S No
Remarks	Other	Other	Kitchen	Utility /-balcony 3-	Utility / balcony-2	Utility / balcony 1	Lebby 1	Dining	Drawing	Foilet 3	Bedroom 3 -(4β)	Toilet 2 (CT)	Bedroom 2 (K6)	Toilet 1 (MT)	Bedroom 1 (MB)	Room
			<	1	\	<	1	<	<	1	<	<	<	<	<	Skirting Provision (• or ×)
			1	1	<	1	1	1	<		1	<u>\</u>	<	<	<	Finishing around door frame (v or x)
			<	1	<	<	,	<u> </u>	<	1	く	<	<	<	<	Beams & columns finishing (v or x)
			<	Ţ	1	1		١	١	((I	١	1	{	Finishing of lofts (• or ×)
			<	1	<	<	1	<	<	1	<	<	<	<	<	Electrical junctions finishing (• or ×)
		.	<	1	1	1	1 1	4	<	١	<	<	<	<	<	Window check ⁶ (v or x)
		-	<	1	(1	1	1	ſ	1	1	<	1	<	1	Tiles provision (• or ×)
			×	1	1	1	1	١	1	1	(<	,	<	1	Sink provision & size (✓ or ×)
			1		<	1	1	1	<	!		< '	<	<	<	Grooves for door frames (v or x)
			1	[1	<	[1	J	1	(J	ı	1	,	Balcony & terrace sill top finishing(v or x)
			1			}	1	٢	1	1	1	<	1	<	1	Screeding in bathroom & utility (• or ×)
			1	1		1	1	1	1	1	1	<	<			Screeding in 6" above FFL? (or x)