Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Proceed with further	Recommendation: Stop further work. S	Checked By MD on	Additions & alterations sheet date	Previous stage report no.	Project Manager 7	Prepared by . 1	Company	Flat No.
Proceed with further work. ATR not required	ubmit ATR on QC rep				Core"	-	Vista Homes	F-304
ing corrections pointed red.	port to QC team. Proc	MD Sign	10/04/19	340HE	Sign	Sign	Project	Other
Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	commendation: Stop further work Submit ATR on QC report to QC team. Proceed only after recheck by QC.		All pages signed by e	Report Hed and signed by PM?	3	Who humas	vista Homes	H
ATR not required.	by QC.	For filling	All pages signed by engineer & customer?	ed by PM?	Date	Date .	Phase	Sl. No.
		☐ Yes ☐ No	✓ Yes □ No	Yes \ No	29/07/19	24/07/19	Continue	34104

Inspection should be done after:

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark **XX** for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- . Fasteners must be used as specified in circular. Especially check fixing of PVC pipes
- 0. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

. .

	Signed by engineer,	Remarks on additions & alteration sheet:			Remarks	15 Other	14 Other	13 Kitchen	12 Utility / balcony 3	11 Utility / balcony 2	10 Utility / balcony 1	9 Lobby 1	8 Dining	7 Drawing	6 Toilet 3	5 Bedroom 3	4 Toilet 2	3 Bedroom 2	2 Toilet 1 \mathcal{W}_{1} .	1 Bedroom 1 M. B _€	S No Room
Signed by engineer, Revised drawing required from HO	s & alteration sheet:	& alteration sheet:						2	1	4	£ .	•	QUI to a	مستنري	The state of the s	18.0%	e e e e e e e e e e e e e e e e e e e	Bd -	Civil work near pipes in balcony & utility (• or ×)		
]Yes ☑No	Yes No									ζ,	< ,	egy X a	7	a societa	Aggretic set	9 5	V.	,	محصري		CPVC & PVC Check (• or ×)
Approv	Signed							<	1	<	4		ν,	4	Gi	0.1·	ζ.	*	V.	V.	Electrical points check
Approved revised drawi	Signed by customer,									4	1	A		Mark Co.	R	8 0 1	۲,	وستار	V		Water proofing check (or x)
drawing attached	[4]								Y	۲.	۲,	4	Barrio III	* .	· ·	1	Ġ	g. (1)	MON YOU	i.k.	Proper use of fasteners check (• or ×)
∃Yes ∏No _	✓ Yes No							(r)		•		, R	All provides	4	F	7	d care	€.	E-7-2 Miles	£.,	Placement of DB (• or ×)
								3			1,00	ę,	a property and the second	4		5	e constitution of the cons	district.	in a		Placement of Generator changeover (• or ×)