## Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Recommendation:  Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	on MD Sign For filling	Additions & alterations sheet date  UNSCIA  All pages signed by engineer & customer?   Yes	aggs 9 Report filed and signed by PM?	Project Manager Subbox Rody Sign Date	Prepared by Sund Sign Date 18	Company BNC Project MFG Phase	E- 505. Other Sl. No.
	☐ Yes ☐ No	? Yes No	Yes No	81/5/18	18/5/18		30282

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

## After Plumbing & Electrical Check.

## Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1"
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

	15 Other Remarks	14 Other	- 🕂 -		10 Utility / balcony l	_	7 Drawing		30	3 Bedroom 2 K. Ded	Toilet 1	1 Bedroom 1 M.Bed		oom
			) !	\	(	1 1	1		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	7		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		Civil work   CPVC & near pipes in   PVC Check balcony & ( • or ×)
			<		1	-	9   3		1	\	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	7		Electrical points check
					21		1	•	· )	<		<	•	Water proofing check ( • or ×)
					\	+		•		5			-	Proper use of fasteners check ( • or ×)
Yes No			1	Ten-		1	1	2			1	1	1	Placement of DB ( v or x)
			\		)	) )	1	7	)	)	;   \			Placement of Generator changeover ( • or *)