## Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Stop further work. Proceed with furthe	Checked By MD on	Previous stage report no	Project Manager	Prepared by	Company	Flat No.
commendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after superceed with further work only after making or Proceed with further work. ATR not required.		Ю.	Subba Reddy	P. San Kumor	BNIC	E 403
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR n  Proceed with further work. ATR not required.	MD Sign	29361	Sign	Sign	Project	Other
eed only after recheck QC report to QC team out in the QC report.		Report filed and signed by	70/6	Prod.	MFG	
by QC. ATR not required.	For filling	d by PM?	Date	Date	Phase	SI. No.
	☐Yes ☐No	LYes □No	811 M 00	20/W/1.8	1=1	30071

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

## Notes:

- Mark v for correct or minor mistake which does not require correction Mark x for minor mistake that requires minor correction.

  Mark x for major mistake that requires correction by replacement or re-fixing.

  Mark x x for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. <u>Plastering must be 3mm margin for luppum work</u>. Tolerance ¼". Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have "grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	15	14	13	12	=	10	9	8	7	6	5	4	ယ	2	-	S No
Remarks	Other	Other	Kitchen	Utility-/-balcony 3	Utility / balcony 2	Utility / balcony 1	Lobby 1	Dining	Drawing	Toilet-3	Bedroom 3 くら	Toilet 2	Bedroom 2 (CB	Toilet 1 MT	Bedroom 1 MB	Room
			X		<b>~</b>	<	<b>4</b>	<	~	!	V	٨,	ς.	ζ.	5	Skirting Provision ( • or ×)
		3	1	,	}	<	-	]	<	1	V	4	<b>\</b>	く	<u>ج</u>	Finishing around door frame ( v or x)
			1	4	イ	<	grade states	1	<	1	~	V	<	У	<b>V</b>	Beams & columns finishing ( • or ×)
			<	-	j	3	· manual	,	J	4	1	1	}	)	ren .	Finishing of lofts ( • or ×)
1			メ	1	<	<		<	<	*****	\	į.	Z,	¥	1.,	Electrical junctions finishing ( v or x)
			4	- 100 m	Ţ	1	1	}	5	4	<	ς	<	<	<	Window check <sup>6</sup> (✓ or X)
9			۲,		1	<	-	1	I		1.1	<	)	<	5	Tiles provision (✓ or 🗙)
			۷,	Agents.	١	5	مدادي	<	5	1	1	<	1	<	,	Sink provision & size ( v or x)
			1	1	1	<.	- areast	١	<	*****	Y,	<	5,	<	<b>&lt;</b> 5	Grooves for door frames ( v or x)
			i	Boymun	<	type Marin	)	1	1	-	1	)	1	,	1	Balcony & terrace sill top finishing( • or ×)
			1	1	9-1	1/2	<b>*</b>	2	)	1	1	K	Same of the same o	<	J	Screeding in bathroom & utility ( • or ×)
			4	Į	1	\$	1		4	Name of the last o	49-1	<	Ì	4	1	Screeding in 6" above FFL? ( v or x)

Quality Control Check Repot. Stage: After Plastering (Apartments)