## Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

	O.D.C.				
Flat No.	アーショー	Other	1	Sl. No.	28818
Company	BIYC	Project	MEG	Phase	Ħ
Prepared by	Sndhw	Sign	4	Date	20/12/17
Project Manager	Subba Reddy	Sign	rest_	Date	7(12)
Previous stage report no.	0.	27834	Report filed and signed by PM?	1 by PM?	NX es □ No
Additions & alterations sheet date	sheet date	88/10/12-	All pages signed by engineer & customer?		Yes No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation:  Stop further work. Submit ATR on QC report  Stop further work. Proceed with work after s  Proceed with further work only after making.  Proceed with further work. ATR not required	Submit ATR on QC re Proceed with work aft rr work only after mak rr work. ATR not requi	commendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck leads further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	y QC. \TR not required.	

inspection should be done after:

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

## After Plumbing & Electrical Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- "." Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Rei	Ren	$\vdash$		13	12		5	9	8	7	6	5 I	4	1	-		+-	No		_	
Remarks on additions & alteration sheet: Signed by engineer, Revised drawing required from HO	Remarks	Other	Other	Kitchen	Lithity / balcony 3	Utility / balcony-2-	Utility / balcony 1	Lobby-1	Dining	Drawing	Toilet3	Bedroom 3 (wb/	1	1	Toilet 1 (PCI)	T U	R	Loor	a 		
alteration shee				1		<	\ \ \		+	1 1		1 1			1	<b>\</b>	X)	utility ( vor	balcony &	Civil work	
T. Yes No					(	1	+	<	1		1		1	<	\	<	5		( or x)	CPVC & PVC Check	   
					<	1	<	<	1	<	<	1	<	<	<	<	<			Electrical points check	•
Signed by customer, Approved revised drawing					1		1	\ \ \ \			1					-	1		check ( or or	proofing	Water
awing attached			-					-		1	\	;		(		•	!		X)	fasteners	Proper use of
Yes UNO						1		1	1			<	1	\	1	1	<b>1</b>	1		DB (vorx)	Placement of
							}	\	1	9	1	<	1	1	1		1	1	( or x)	changeover	Placement of
				1_	<u>L</u> _		1_						- 1000	W.							