Quanty	0
Collina	Control
I CHECK INC	Charly Da
CHECK INCOME	not
Company of the same of the	Stage: Al
l	ter Plast
	ering (Ap
١	artments)

					7
Flat No.	C-180	Other		SI. No.	28853
Company	5-12	Project	Pmr-II	Phase	F
oy /	wor	Sign	P.C.	Date	02/01/2018
ager	Sign Sign	Sign	ACL	Date	02) 61)2018
Previous stage report no.	なるなり	S S S S S S S S S S S S S S S S S S S	Report filed and signed by PM?	d by PM?	Yes No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making of the proceed with further work. ATR not required	ubmit ATR on QC re Proceed with work af work only after mak work. ATR not requ	port to QC team. Proces resubmitting ATR on ting corrections pointed ired.	scommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	y QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ken	ָדֶּין בּי	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	S No
Kemarks	Sort To	Other	Other	Kitchen	Utility / balcony 3	Utility / balcony 2	Utility / balcony 1	Lobby 1	Dining	Drawing	Toilet-3-	Bedroom 3	Toilet 2 CT	n 2		Bedroom 1 705	Room
				/	•	<	<u> </u>	}	<	`	-	1	<	<	<	<	Skirting Provision
				•	•	`	<,	١	ĺ	<	!	1	۷,	<	ζ.		Finishing around door frame (• or ×)
				<	•	۷,	ζ,	1	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	<	1	Ţ	<	<,	<	√.	Beams & columns finishing (• or ×)
				۷,	1	1	{	ļ	ļ	1	٢		}	******	5	3	Finishing of lofts (• or ×)
				K	\$	<.	<	1	<,	<	1	1	< ,	\	<	<	Electrical junctions finishing (v or x)
				<	1	١	J	١	١	<	ļ	1	1	<	ς,	<	Window check ⁶ (✓ or X)
				<	}	١	<	1	1	1	1	}	/	1	<,)	Tiles provision (• or ×)
				<	1	1	<	1	ſ	1	Ţ	[<	1	<	1	Sink provision & size
				j	1	١	<	١	1	<	ſ	}	<	\	<	<	Grooves for door frames (• or ×)
				1	-	<	, ,	(Ţ	j	(1		1	i	1	Balcony & terrace sill top finishing(• or ×)
				1	(1	<	1	1]	1)	<	1	•	1	Screeding in bathroom & utility (v or x)
				1	ţ	1	<	1	(1	-	1	<		<	1	Screeding in 6" above FFL? (✓ or 🗙)