Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No.
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Q Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.		no.	Kashinih Kamar Sign	P. Car Kenner Sign	Porr-11	(2-32) Other
port to QC team. Proceed the submitting ATR on ting corrections pointedired.	MD Sign	285 44	Sign	Sign	Project	Other
eed only after recheck QC report to QC team I out in the QC report.		Report filed and signed by	£,	Phase		
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	Sl. No.
	☐Yes ☐No	MYes □No	20/2/18	20/2/18	E)	29407

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XX for major mistake that cannot be corrected.

 9"unplastered area from SFL should be left including in common areas and terraces.

- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

		7			Ī					1					П				1	
Screeding in 6" above FFL? (\checkmark or \times)		7	c	٠,	:		(:	د	1.4		}							
Screeding in bathroom & utility (\checkmark or \times)	Ļ	>	(^	7	¥			3	7		-	(
Balcony & terrace sill top finishing (\checkmark or \times)		·	٠			\- <u>-</u> 1	ļ	•		i.										
Grooves for door frames (v or X)	,			1			. ^	3	:• :	· ^	`	į	agent and							
Sink provision & size (* or *)	(5	ſ	>				ì	1.0	٠	Ì	book	>							
Tiles provision $(v \text{ or } x)$	1	٠,٠	1	>	,, ~ *		,		141	, \	ì	-	7							
Window check ⁶ (∨ or ×)	>	5	>	>		٠	, i		121	1	1	1	^/				•			
Electrical junctions finishing ($\checkmark \text{ or } X$)		>	5	\				,	30.5	>	>	1	`\					8		
sitol to gnidsinif (× 10 v)	i	, J	j	}	, ,	Į.		·	,	1	}	(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					5 5 5		
Beams & columns finishing (\checkmark or \times)	>	7	7	1	1			ک ا		>			/							
Finishing around door frame (> 10 or >)	1	7	7	1	*		د	,	;	>	1		!							
Skirting Provision	د	>	×	>		5	د	×	í	1	>	1	, >							
Коот	Bedroom 1 №13	Toilet 1 MT	Bedroom 2 1213		Bedroom 3	Toilet-3	Drawing	Dining	Lobby 1	Utility / balcony 1	Utility / balcony 2	Utility/balcony 3	Kitchen	Other	Other	Remarks				
°N S	_	7	3	4	5	9	7	∞	6	10	1	12	13	14	15	Reı	i			