//

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No.	404	Other	4	Sl. No.	32'547
Company	vista Homes	Project	vista umes	Phase	1
Prepared by	Sikuldeep	Sign	Fulder	Date	03/01/19
Project Manager		Sign		Date	03/01/19
Previous stage report no.	10.	26607	Report filed and signed by PM?	d by PM?	√Yes □ No
Additions & alterations sheet date	s sheet date	21/12/18	All pages signed by engineer & customer? Yes \(\subseteq \text{No} \)	gineer & customer?	∠Yes □No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Sub Stop further work. Proceed with further work. Proceed with further work. Sub Proceed with further work.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck l Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	port to QC team. Proce er submitting ATR on ing corrections pointed ired.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	by QC. n. ATR not required.	•

nspection should be done after:

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request

After Plumbing & Electrical Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- 10. Height of DB box must be 6" below false ceiling level or 12" below slab level
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Yes No		Approved revised drawing attached	Approv	Yes No	from HO	required f	Revised drawing required from HO	Revi
Yes	S	Signed by customer,	Signed 1	Yes No	[T]	er,	Signed by engineer,	Sign
					Remarks on additions & alteration sheet:	tions & alı	arks on addi	Rem
							Remarks	Ren
				5			Other	15
1	1	7	Ţ	*	1		Other	14
1	1	1	`	7	1		Kitchen	1.3
1	1	1	1	•		сопу.3	Utility / balcony_3	12
1	ı		ς .	<	<	cony 2	Utility / balcony 2	=
1)	1	7	ζ	<	cony 1	Utility / balcony 1	10
1	Ţ		Barrer.	1	1		Lobby	9
ſ	1	Į	<		1		Dining	8
<	I	1	<		1		Drawing	7
1	(ſ	ţ	Ę			Toilet-3	6
1	1	-	1	, ,,,,,,	•		Bedroom-3	5
[Ź.	<	X		C.T-	Toilet 2	4
1	1	Į	<	1	*harr	と・B	Bedroom 2	3
I	•	7	ς .	(1	L. W	Toilet 1	2
1	1	t	7	1	١	70. B	Bedroom 1	1
	OI.	check (✓ or ×)	(v or x)	(• or ×)	balcony & utility (• or ×)		Room	S No
Placement of DB (• or ×)	Proper use of I fasteners I	Water	Electrical points check	PVC Check	Civil work near pipes in			