Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Project Manager Project Project Manager SHIR(SH) Sign Sign Date Date OS 03 18	Flat No.	C-421	Other		Sl. No.	£429B
Date n Q883 Report filed and signed by PM? Sign	Company	PMR	Project	PMR	Phase	(=)
Report filed and signed by PM? Report filed and signed by PM? New Year	Prepared by	- 2	Sign	FP	Date	28/1.08/03/18
Report filed and signed by PM? Sign	Project Manager		Sign	the second	Date	08/03/18
All pages signed by engineer & customer? Sign	Previous stage report	no.	29283	Report filed and signe	d by PM?	NYes No
To QC team. Proceed only after recheck by QC. ubmitting ATR on QC report to QC team. corrections pointed out in the QC report. ATR not required.	Additions & alteration	ns sheet date	28/12/17	All pages signed by er	eer & customer?	NY es □No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	2	MD Sign		For filling	☐Yes ☐No
Inspection should be done after:	Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Submit ATR on QC re Proceed with work aft ner work only after mak ner work. ATR not requ after:	port to QC team. Proceed ter submitting ATR on ing corrections pointed ired.	eed only after recheck be QC report to QC team. I out in the QC report.	y QC. ATR not required.	

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

- Mark v for correct or minor mistake which does not require correction Mark x for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1". Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Revised drawing required from HO	Signed by engineer,	Remarks on addition		Remarks	15 Other	14 Other	13 Kitchen	12 Utility/balcony-3	11 Utility /-baleony-2	_	9 . Lobby !	8 Dining	7 Drawing	6 -Toilet 3	5 Bedroom 3	4 Toilet 2 (C	3 Bedroom 2 (&	2 Toilet 1 (ነ	1 Bedroom 1 (S No Room
quired from HO	•	Remarks on additions & alteration sheet:		SEE SECTION SEE SECTION SECTIO	380000		1	1	19 ²	ny 1		1	1	-	1	1	(S)	M7)	7B)	near pipes in balcony & utility (• or ×)
☐ Yes ☑ No	⊠Yes □No	it:		#11072000 E0011195000730004			1	1	<	<	1	1	J	{	1	<	1	<	•	n PVC Check (• or ×)
awing attached	Signed						<		<	<		<	<	1	1	4	<	<	<	points check (• or ×)
	Signed by customer,						1		1	1	1	(-	1]	1	1	1	1	proofing check (v or x)
							1	1	1	1	[/		1	,	(1	1	fasteners check (v or x)
Yes No	YYes □No	1 '					1		1	Que de la constitución de la con	1	1	<	1)	(1	1	1	DB (v or x)
							1	1	l	J		1	<		}	•	*	1	1	Generator changeover (• or ×)