Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

)	7		
T.Tat INO.	0-004	Other		Sl. No.	32961
Company	Vista Homes	Project	vixter womes	Phase	
Prepared by	S. Kuldeep	Sign	Sudden	Date	21/2/19
Project Manager	Tmadhu	Sign		Date	21/02/19
Previous stage report no.	no.	29796	Report filed and signed by PM?	d by PM?	Yes No
Additions & alterations sheet date	s sheet date	21 01 19	All pages signed by engineer & customer?	gineer & customer?	LYes No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck to Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	port to QC team. Proce er submitting ATR on ing corrections pointed red.	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.	y QC. \TR not required.	
inspection should be done after:	after:				

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark × for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

	Revi	Sign	Kem			Ren	15	1,4	13		5 =	1.0	3	9	0	1 0	7 (<u>م</u> .	4	w	2	F	Si	No.	-	- 72
толива пописа пописа	sed drawing require	Signed by engineer,	Remarks on additions & alteration sheet:			Remarks X - 1	Other	Other	Kitchen	Utility / balcony 3	Ourity / balcony 2	Hulity / balcony 1	ьовру 1	Dining	Drawing	roner 2	Toilat 3	۵		Bedroom 2 k.B	Toilet 1 m.T	Bedroom 1 m. B		om	1	
-	1		alteration sheet:			agrands			1		<	7	1	1	1	1		ļ				1	×)	balcony &	near pipes in	Civil work
res	- 1	Yes No				toilut 4		•	*	1	1	(l	1	7		1	X		1		1		(or x)	PVC Check	CPVC &
Approve		Signed b			`	n(w.c)	1		(7	1	1		7	Ą	<	7	<		5	7		(or x)	points check	Electrical
Approved revised drawing attached		Signed by customer,			1	Brik wall			(1	\	1		1	!	1	-	<	•			•	×	check (vor	proofing	Water
	┞-					294			(!		1	1	•	1	1		ſ	1	<		1	×	check (v or	fasteners	Droner nea of
Yes No	ĺ	Yes No				contacted.			1)	1	1			1	1	1	1	1	P. 001	1	1			DB (v or x)	Diagonates
										1		1	1	1		1	Ī	1	†	Į			(or x)	changeover	Generator	מ