Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No.	D-105	Other	1	Sl. No.	808£8
Company	BNC	Project	SEC	Phase	=1
Prepared by	M-Tela Sticher Sign	Sign	10	Date	t1/80)t1
Project Manager	& V Subba Reddy	Sign	roll	Date	+1/30)+1
Previous stage report no.	no.	27399	Report filed and signed by PM?	d by PM?	NYes □No
Additions & alterations sheet date	ns sheet date	Unsold Flat	All pages signed by engineer & customer?		☐Yes ☐No _
Checked By MD on		MD Sign	100 C	For filling	☐Yes ☐No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck loop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	port to QC team. Proceed the submitting ATR on ing corrections pointed ired.	ecommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	y QC. ATR not required.	,

Inspection should be done after:

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark X X for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- . Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

(]Yes □No	ing attached [Approved revised drawing attached	Approv]Yes □No	from HO	Revised drawing required from HO
	Yes No		Signed by customer,	Signed	☐Yes ☐No		Signed by engineer,
				Unsold Flat	4	Iteration sheet:	Remarks on additions & alteration sheet:
	a		a deputation of the second		in the second		D.
							Remarks
							15 Other
			2000		100		14 Other
		1		<	}	-	13 Kitchen
	1	1		(1	1	12 Lility/balcony-3
١	1	1	ſ	4	<	4	11 Utility / balcony 2
1	p. delimin		-	<	<	<	10 Utility/balcony 1
	Ī	-	1		-	1	9
	1		1	<		(8 Dining
<	<	1	1	<		\	7 Drawing
1		-	-	I			6 Teilet-3
1	(((<	•	(5 Bedroom 3 (ч <i>β</i>)
1	1	(ı		<	•	4 Toilet 2 (Cτ)
1	1	- Carrier - Carr	١	<	1	Ī	3 Bedroom 2 (Kb)
J	I		*******	<	۷,	1	2 Toilet 1 (MT)
1	1	5	1	۷	1		Bedroom 1 (MB)
Generator changeover (v or x)	DB (• or ×)	fasteners check (or x)	water proofing check (v or x)	Blectrical points check (v or x)	CPVC & PVC Check (v or x)	Civil work near pipes in balcony & utility (• or ×)	S No Room