## Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No.	D-123	Other		SI. No.	32736
Company	PMR-H	Project	PMR-I	Phase	#
Prepared by	V-Sankoth	Sign	7.2.4	Date	24/01/19
Project Manager	K. Shisish	Sign	RI	Date	24/01/19
Previous stage report no.	no.	27744	Report Med and signed by PM?	i by PM?	Yes No
Additions & alterations sheet date	ns sheet date	9   19	All pages signed by engineer & customer? \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	gineer & customer?	√Yes □No
Checked By MD on		MD Sign	e de la companya de l	For filling	☐ Yes ☐ No
Recommendation:  Stop further work. Sub Stop further work. Pro Proceed with further w Proceed with further w	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	port to QC team. Proceer submitting ATR on ing corrections pointed ired.	eed only after recheck b QC report to QC team. I out in the QC report. A	y QC.	

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

## After Plumbing & Electrical Check.

## Notes:

- Mark v for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

		1 0	2	الح		Ţ-		) 		T_	Γ	T.	Т	_	-		Γ-	т.		T-			¬		<u> </u>			
	evise	ignec		emai				Remarks	15   0	+-	13	+	+	1 1	7	9	8		ļ.,	, U	4	w	7	) -	S	No	)	
	Revised drawing required from HO	Signed by engineer,	at a catalogue oc all	Remarks on additions & alteration		多けっる	Common Common		Other	Other	Kitchen	Uthty/balcony-3	Unity / balcony 2	This // balcony 1	[H43]	Lebby-1	Dining	Drawing	Toilet 3	Ţ	Toilet 2 C-76;	Bedroom 2 片。B	Toilet 1 M. To:	Bedroom 1 M.B	R	LOOI	n	
	om HO Yes	√ Yes	cration sneet:	orotion 1			Total				1	!	۷	(	1		1	1	1	1	(	1	1		×	utility ( or	near pipes in	Civil work
	es WNo	es No					We arrive to K not	.				1	<	<	ſ	1		9	1	1 3	(字)	1	۲ ا	ŗ		( v or x)	PVC Check	CPVC &
	Approved	Signed by			Changeme not at speci	,	Knot of			<	. 1		۲	<	1	<	<	,		<	,					( or x)	čk	Electrical
	Approved revised drawing attached	Signed by customer,			et at spe		pen specified				}	\ \ \		1	,   	1		1		· ·	1	<b>く</b>			Š	check (v or	proofing	Water
一		VYes		,	rigidal heigh					1	****	1			•   •	1	1	1		L	1	<			×	check (v or	fasteners	Proper use of
ļF	Пſ	Yes No			ht.					!	! !	٩					۷	<b>,</b>	1	Ţ	,	ſ	Ą			(* of *)	Placement of	D1- 6
										1	1	1	1		1		, ye.	P	(	1	1	1	•	( = 24)	( v or x )	Changeover:	Placement of	