Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No.	D-203	Other	1	Sl. No.	28067
Company	BNC	Project	スス	Phase	1
Prepared by	M. Tega Svidher Sign	Sign	At	Date	41/00/18
Project Manager	SV-Subba Redy Sign	Sign	roch	Date	41/20/12
Previous stage report no	10.	315tB	Report filed and signed by PM?	d by PM?	NYes □No
Additions & alterations sheet date	s sheet date	4/02/17	All pages signed by engineer	ngineer & customer?	& customer? Yes No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Sub Stop further work. Pro Proceed with further w Proceed with further w	commendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck! Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	port to QC team. Proceer submitting ATR on ing corrections pointed red.	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	y QC. ATR not required.	

ispection should be done after

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark **X** for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark **XX** ior major mistake that cannot be corrected.
- Location of (PVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- 10. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- 11. In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Reviso	Signed	Remai			Remarks	15 C	14 C	13 K	12 L	111	10 E	1 6	1 8	7 <u>I</u>	6 T	5 E		3 E		1 E	S No	
Revised drawing required from HO	Signed by engineer,	Remarks on additions & alteration sheet:	2) Them	net	rks Not. 1) &	Other	Other	Kitchen	Utility/balcony3	Utility / balcony 2	Utility+balcony 1	Labby 1	Dining	Drawing	T oilet- 3	Bedroom-3	Toilet 2 (CT)	Bedroom 2./ [(13)	Toilet 1 (ドナ)	Bedroom i (ዣይ)	Room	
from HO	רק	Iteration sheet:	on were	as her	n Drawing				(<	<	[\		Section of the sectio		(1	1	e personal de la constanta de	balcony & utility (• or ×)	near pipes in
Yes No	Yes No	\	e Some	Spechications	\			<	-	<	۲,	ſ	1	1	-	1	<		<	1	(• or ×)	PVC Check
Approv	Signed by customer, YYes \(\subseteq \text{No} \)		waternat	, a	Kitchen, R. M. Bedroom.			<	(\	〈	ſ	<	<	1		4	Υ	<	<	(• or ×)	points check
Approved revised drawing attached			- Customer Changes.		room. On				-	1]	(1	1	1	check (✓ or	proofing
ing attached Yes No					u Switch Board				(1		}	1			1		-	check (or	fasteners
								+	[ļ	1	<		1	•		1	ļ		DB (v or x)
					hight is			1	1		1	1	1	<	1	1	1		J	4	changeover (• or ×)	Generator