Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No.	_	Other		SI No	)
	17 - 607				28222
Company	BNC	Project	プ ウ ウ	Phase	F
Prepared by	P. Six Kunn	Sign	Porch	Date	4/2/1
Project Manager	S. V. Subba Mcdes Sign	Sign	resi	Date	16/10/17
Previous stage report no.	0.	45847	Report filed and signed by PM?	d by PM?	Nyes   No
Additions & alterations sheet date	sheet date	12/4/12	All pages signed by enginee	r & customer?	∏Xes □No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation:  Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making of the proceed with further work. ATR not required.	commendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck I Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	port to QC team. Proce er submitting ATR on ng corrections pointed red.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	y QC. (TR not required.	
Inspection should be done after	fer.				

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Bleetrical Check.

- Mark  $\vee$  for correct or minor mistake which does not require correction. Mark  $\times$  for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as pcr measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- 11. In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Revised drawing required from HO Yes No	Signed by engineer,	Remarks on additions & alteration sheet:	Remarks on additions & alteration sheet:	D 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						to a reason to the second seco			Remarks	Other	14 Oner	+	13   Kitchen	12 Utility baleony-3	00 00000	_		9 Lobby-1	8 Dining	7 Drawing	6 Toilet-3	5 Bedroom 3 Gb	4 Toilet 2 CT -	3 Bedroom 2 KB	Toilet 1	1 Bedroom 1 Nb		m balcony & ( or x)	near pipes in PVC Check	
Approved	Signed by customer,																<	Ţ	<	<		1	<	<	1	<	<b>ر</b>	<	<	<		( v or x)	points check   p	_
Approved revised drawing attached	customer,									-			]		1	<		•	{	1	1	<	<u> </u>	1	<	1	×							
																	}		<	<	,		1	J		\	)	)	•	}	×	heck (v or		
Yes No	Yes No											The state of the s		201			1	1	-	1		1	}	<	1	)	)	\	)	)		2	DB (v or x)	
											 		-1	3			)	}	1	)	,	)	]	<	1	1	1	1		1	( • or ×)	changeover	Generator	