Quality Control Check Repot. Stage: After Plastering (Apartments)

Interval is at No. In the company and the company and the company and the company and the company after making corrections pointed out in the QC report. ATR not required. In the company after making corrections pointed out in the QC report. ATR not required.	Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after submit ATR on QC report Proceed with further work only after making of Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager Subba Reddy	Prepared by M. Tega Sridher	Company BNC	Flat No. 0-702
Sl. No. MF4 Phase Phase Date Report filed and signed by PM? For filling occeed only after recheck by QC. on QC report to QC team. ted out in the QC report. ATR not required.	Oreport to QC team. Prrk after submitting ATR making corrections poin required.	MD Sign '	27954		w. Sign	Project	Other
Sl. No. Phase Date Date ded by PM? For filling by QC. ATR not required.	oceed only after recheck on QC report to QC team ted out in the QC report.		Report filed and sign	roll	WI	MEG	1
	by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed,
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Re	15	14	13	12	=	10	9	∞	7	6	5	4	w	2	_	S No
Remarks	Other	Other	Kitchen	-Utility/balcony.3	Utility/balcony-2-	Stility / balco	Lebby-h	Dining	Drawing	Tailet 3	Bedroom 3	Toilet 2 (Bedroom 2	Toilet 1 \	a 1 (Room
	3			my.3	ny-2	ny 1					(gn)	(τ)	ks/	제진	(gh)	
			<	ſ	<	<	-	<u> </u>	<	-	√	Y	~	<	<	Skirting Provision
			<	!	۷,)		1	<	1	<	<	<	<	<	Finishing around door frame (v or x)
			<	1	4	<		<	<	(1	〈	<	<	<	Beams & columns finishing (• or ×)
			<	1	j	1	-	1	}	Ţ	١	ſ	-		j	Finishing of lofts (v or x)
			<	1	<	<		<u> </u>	<	I	<u>ر</u>	<	〈	<u> </u>	<	Electrical junctions finishing (v or x)
			<	1	(-	4	-	1	1	<	<	<	<	<	Window check ⁶ (✓ or ×)
			<	1	1	j	•	1	}	-	١	<	ļ	~	1	Tiles provision (✓ or 🗙)
			<	{	1	1	-		1		1	<	١	~	1	Sink provision & size (✓ or ×)
			١	1	<	1	-		(l	~	Υ.	<	<	<	Grooves for door frames (• or ×)
			-	1	1	1	•	1	1	1	\	1	•	1	J	Balcony & terrace sill top finishing(• or ×)
			1	1	<			1	1	9		<	1	<	1	Screeding in bathroom & utility (• or ×)
			1		<		l	1	1	1	-	<	J	<)	Screeding in 6" above FFL? (v or x)