Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

			I							
Proceed with furth	Proceed with furth	Stop further work	Recommendation:	Checked By MD on	Additions & alterations sheet date	Previous stage report no.	Project Manager	Prepared by	Company	Flat No.
Proceed with further work. ATR not required	er work only after mak	Proceed with work af	, , , , , , , , , , , , , , , , , , ,	p.	s sheet date	no.	Subba Reddy	M. Teja Sridher	BNC	0-803
iired.	Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Stop further work Proceed with work after submitting ATR on OC report to OC team		MD Sign	Unsold flat	4th38	Sign	Sign	Project	Other
	out in the QC report.	eed only after recheck to OC renort to OC team			All pages signed by engineer	Report filed and signed by PM?	Tell	94	MFG	
	ATR not required.	oy QC.		For filling	ngineer & customer?	d by PM?	-Date	Date	Phase	SI. No.
				☐Yes ☐No	□ Yes □ No —	☐Yes ☐No	24/11/12	24/11/12	币	28480

inspection should be done after:

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request

After Plumbing & Electrical Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- 10. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- 11. In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

	points check proofing check (v or check (v or x)) check (v or check (v or check (v or x)) check (v or check (v or check (v or x)) check (v or check (v or check (v or x)) check (v or check (v or check (v or x)) check (v or check (v or check (v or x)) check (v or check (v or check (v or x)) check (v or check (v or check (v or check (v or x)) check (v or check (v or check (v or x)) check (v or check (v or check (v or x)) check (v or check (v or check (v or x)) check (v or check (v or check (v or x)) check (v or check (v or check (v or x)) check (v or check (v or check (v or x))) check (v or check (v or check (v or x))) check (v or check (v or check (v or check (v or x))) check (v or	Revised drawing required from HO Yes No.	Signed by engineer,	Remarks on additions & alteration sheet: Unsold											Kemarks	-	15 Other	-	14 Other	I.) MICHAIL		12. Churty / network 2	1	11 thinly thatemy -	Trible / bullman 7	In Chity Hancony i a	_	, LAURAL C		2 Dinung		7 Drawing	0 telleto	Tailat 2	5 Bedroom 3 (4β) / /	4 1011ct 2 (11/ - V	Toilar o	3 Bedroom 2 (KB)	7 Tollet 1 (ALL)	H :1-41	1 Bedroom 1 (内的) — — —	Ro unity (or	on		near pipes in PVC Check	TOWNSHIP TO THE REPORT OF THE PROPERTY OF THE
fastene check x)	fasteners check (v or x) Check (v or x) DB (v or x) Provided Pr	(1	22																	_ < _		1	1	1	•		•	•	<u></u>		,			<u> </u>			<	2	_				2000	points check	
_ 1	DB (or x)	ised drawing attached	tomer,														3				({		:						-						-	Tage of the same o					×	check) -