Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No.	6-305	Other	ĺ	SI. No.	29953
Company	BNC	Project	MFG	Phase	1
Prepared by	M. Teja Sridher	Sign	the state of the s	Date	10/04/18
Project Manager	Subba Reday	Sign	1.2	Date-	10/04/18
Previous stage report no	no.	89811	Report filed and signed by PM?		MYes □No
Additions & alterations sheet date	ns sheet date	41/11/12	All pages signed by engineer & customer? \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	gineer & customer?	Yes No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	ecommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	port to QC team. Proceer submitting ATR on ing corrections pointedired.	eed only after recheck b QC report to QC team. I out in the QC report. A	y QC. ATR not required.	
Inspection should be done	er work. ATR not requaler:	ired.			
Inspection should be done after:	after:				

aspection should be done after

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of cmail by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

Notes:

- Mark v for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- 0. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Rev	Sign	Ren		Ren	15	14	13	12	=	10	5	×	7	6	S	4	w	2		S No
Revised drawing required from HO	Signed by engineer,	Remarks on additions & alteration sheet:		Remarks) (Other	Other	Kitchen ,	1 tility / bulcony 3	Utility / buleony 2	Dillity / buleony 1	Lubby 1	Diming	Drawing	Toilet 3	Bedroom 3 (46)	Toilet 2 (CT)	Bedroom 2 (KB)	Toilet 1 (Mr)	Bedroom 1 (MB)	Room
from HO	ĸ	alteration sheet:		Wall mixtures			١	1	〈	?			•		1	ſ	1	J	ſ	Civil work near pipes in balcony & utility (< or x)
Yes No	¶Yes □No			u net			1	1	<	<	1		ţ		\	<	1	<	1	CPVC & PVC Check
Approve	Signed 1			Rovided			Y		く	<	1	<	<		√	~	۷,	〈	<	Electrical points check
Approved revised drawing attached	Signed by customer,			s wild			•		1		-	ţ		1	(1	ı	1	1	Water proofing check (• or ×)
ng attached	K			12					\	,			(1	(1	1	1	1	Proper use of fasteners check (• or ×)
]Yes No -	☑Yes □No					2 1000 10000000 00	-		1	Y	-	1	<	بدسيف	(ı	ſ	1	}	Placement of DB (• or ×)
\									1	1			<		ſ	ſ	1	1	J	Placement of Generator changeover (• or ×)