Quality Control Check Repot. Stage: After Plastering (Apartments)

	Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making of the proceed with further work. ATR not required	Recommendation	Checked By MD on	TICVIOUS SIAGE TEDOIT NO.	Pravious store road	rioject ivianager	Droingt Manage	Prepared by	Company	Company	Flat No.	
	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not Proceed with further work. ATR not required.			10.		Obbba Reddy Sign	LEGO ON ONE	Sign Cadlar Sign	BNC		F-102	
	port to QC team. Proce er submitting ATR on ing corrections pointed ired.	TIBIO CIM	MD com	となったな)	Sign	ď	Sign	Project		Other	
	eed only after recheck QC report to QC team l out in the QC report.			Report filed and signed by PM	her	20 "	7		マナで		1	
	by QC. ATR not required.	For filling		ed by PM?		Date	Date	Data	Phase		Sl. No.	
		∐Yes ∐No		NYes No	ブーノーニー	7110112	<u> セーク ニー</u>	-\\^	=)	10001	70/21	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check. Notes:

- Mark V for correct or minor mistake which does not require correction

 Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.

- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Kei	D Pt	15	14	13	12	11	10	9	8	7	6	5	4	ω	2	1	S No
Remarks	marica	Other	Other	Kitchen	Utility/balcony3	Utility / balcony-2	Utility / balcony 1	Lobby-1	Dining	Drawing	Teilet-3	Bedroom 3 (いち)	Toilet 2 (CT)	Bedroom 2 (KB)	<u> </u>	Bedroom I (MB)	Room
				<		〈	<	1	く	<	j	7	. <	~	<u>\</u>	<	Skirting Provision (• or ×)
			TOTAL DESIGNATION OF THE PARTY	١	1	4	}	1	1	<		7	۷,	~	<	<	Finishing around door frame (v or x)
		200		<		~	<	1	4	ς	-	<	<	<	く	<	Beams & columns finishing (v or x)
			20 30	<	1	1	ſ	1	l	1	1	1	i	1	ı	1	Finishing of lofts (• or ×)
				<	1	<	<		<	<	-	く	<	ζ	<	<	Electrical junctions finishing (• or ×)
				<	I	1	Į	-	1	ţ	1	<	<	<	<	<	Window check ⁶ (✓ or ×)
				<	I	1	1	1	1	ſ	ļ	1	<	(<	}	Tiles provision (• or ×)
				<		Ì	İ		1	}		1	<	1	<	j	Sink provision & size
				1	1	<	١	1	1	<	-	Ų	<	<	<	<	Grooves for door frames (v or x)
					1	1	1	1	1	1	1	1	١	1	1	ı	Balcony & terrace sill top finishing(• or ×)
		•		Ì		Ł	J	1	1	1	1	(<	1	<	-	Screeding in bathroom & utility (v or x)
				1	1	<	1	1	-	1	1	1	<	1	<	-	Screeding in 6" above FFL? (v or x)