Inspection should be done after:

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check,

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- . Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
-). Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- 10. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Remarks on additions & alteration sheet: Signed by engineer, Revised drawing required from HO	Remarks	14 Other 15 Other	+	12 Utilitybalcony 3	11 Utility / balcony 1	+-		7 Drawing	6 Reilet-3-	4 Toilet 2 67. 7	Bedroom 2		S No Bedroom I M 22
ration sheet: Yes No			* !	×	X			Sept	<u> </u>	j	į	١ /	Civil work near pipes in balcony & utility (• or x)
		<		7	<	1					<		CPVC & PVC Check (• or ×)
Signed by customer, Approved revised dr		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	A. China	7 9		<	5	1		<	<	(Electrical points check
Signed by customer, Approved revised drawing attached			1			1	1	Q		(See on)	5	1	Water proofing check (• or ×)
ttached Yes			K	5		1			ζ,	j			Proper use of fasteners check (v or x)
s				•		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		G1	Ligation				Placement of DB (• or ×)
		p d amon		1		5	COTTON NO.		()	,	\$		Placement of Generator changeover