	9
	12
-	lit
	y Control Check Repot.
	\mathbf{C}
Ì	n
	tr
	0
j	
	h
	ec
į	K
i	$\overline{\mathcal{R}}$
1	ep
	2
ĺ	
	S
	ta
1	ge
	• •
	Af
	te
	r
	$\mathbf{B}_{\mathbf{I}}$
	ic.
	k
	WC
.	ī
1	~
i	Stage: After Brickwork (Apartments)
1	30
	Ξ
	Œ
	e
	\mathbb{R}^{n}
	(2)

Flat No. Chers	Sl. No.	78248
May Project	VISTO Homes Phase) 1
	Date Date	16/9/19
Project Manager T. Machil Sign . Multum	Date Date	16/9/10
Previous stage report no. 33366 Report filed and	Report filed and signed by PM?	Yes No
Apartment No Other	Other	
Checked By MD on MD Sign	For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	fter recheck by QC. t to QC team. e QC report. ATR not required.	ired.

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork Check.

- Mark ✓ for correct or miner mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2" to 3" thickmess with one no. 6 mm or 8 mm rod with M15 CC
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- Balcony sill level should be 3'3" from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

	Rer	15	14	13	12	11	10	9	8	7	6	S	4	3	2		S No
MOSTAL Y	Remarks Trastee	Other	Other	Kitchen	Utility/balcony 3	Utility / balcony 2	Utility/balcony 1	Lobby-1	Dining	Drawing	Toilet 3	Bedroom 3 (5) 40 40	Toilet 2 Can think	Bedroom 2 尺、β い	Toilet 1 M. Toi	Bedroom 1 M.Bed	Room
Pa	<u></u>				in the second	<	ţ	,	, man	Ĺ		{	(5	Ć,	ζ	Wall thickness (• or ×)
20					* 1	(<	1		ζ,	i			-		,	Beds in walls (• or ×)
() 2. E.Y	200				P	<	Ç	F	<u></u>	ŗ	# TT T G. 1	Ę		(ζ	ς.	Chicken mesh
Bide						<	ζ,	- Carrier	95-100	ς,	Name year	C-10-1	h	Dis Pilabe	E. sort		External brickwork & beam joint (• or ×)
(4)	50 5				g v	ζ	ς,		9	3	garn) de	(ζ.	۷,	1	ζ	Room Dimensions (• or ×)
077	1				Service on Live	E was equipment	7	r interest	7.114	Carlon .	and the state of	STAIL .	C: 31cmare	- Control	N. 11-11-11	annount. C	Room Dimensions Difference in inches
STUE A	0.66		•	ė	Selection.	<	<	E (District	Į.	(Company of Assessment	<.	ζ	S	<	<	Diagonal
Sax.					9	1	Transmu.	Paris (Albana	Ellena	Stephen damen ben	Contraction of Contra	e-tourne.	22.43	Constitution of the last of th	C/CHRAP		Diagonal Difference in inches
	方の				1	(<	profit constituent	BETTY MANAGEMENT	1	D.III.		(?	<	<	Balcony sill level
					-	Ć.	?	Page 4 agent	OT STATE OF THE PERSON NAMED IN COLUMN TO STATE OF THE PE	<		ζ,	<	<	<	<	Room Height (✓ or X)
	Colabb				7 11 15 444		1 (1) I am		7	-				AVO	Plumb of walls (Good/Avg./Bad)
	1/2/				1	1)	1	3	7	1)	,	1	1		Alignment of beams and walls - Nos.

Quality Control Check Repot.	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	Good Avg. Bad
Specify rooms that need correction:	
Misc. Checks.	
Was 3.75 CFT proportion box provided?	Yes Yo
Condition of proportion box?	☐ Good ☐ Avg. ☐ Bad
Was the Apartment cleaned before starting brick work?	Yes No Cant' say
Is the Apartment cleaned for plastering?	□Yes □No
Wastage?	High Medium Low
Storage of building material like bricks sand and cement.	☐ Good ☑ Avg. ☐ Bad
Drum (200 lts) provided for curing in each flat?	□Yes □No
Remarks:	

Door Frames & Windows check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark \times for minor mistake that requires minor correction.
- Mark **XX** for major mistake that requires correction by replacement or re-fixing. Mark **XXX** for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 1/2" after plastering.
- Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 35" or 36"from SFL.
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

		Ren	15	14	13	12	11	10	9	~	7	6	S	4	ω	2	-	S No
		Remarks:	Other	Other	Kitchen	Utility/balcony-3	Utility / balcony-2-	Utility/balcony 1	Lobby 1	Dining	Drawing		Bedroom 3 (51 BCd	V 1	Bedroom 2 K - Ocu	_	Bedroom I M. Bed	
					C. C	and the state of t	<		0	42,	(ł	ζ	(((<	Door size, face and position (• or ×)
					4	egy jiyan hasan	<	•	1	typ mark	<	Ber Jones	· ·	(((<	Brick at bottom of door frame (• or ×)
					4	a vie	ς	and the second	by rem	N/Mar-	Υ.		((((<	Door lentil level (• or ×)
					•	(gapes)	ζ	£ 2500 mmm		E1114mm	۲.	Elizabeth Comment	(((<	Door diagonal check (• or ×)
					1		<	· Chire	auto-rene	(C)	<		<	(((<	Door Plumb - two sides (vor x)
						1	ζ,		f - All management	November 1	<	F 11. 100	<	(((ζ	Door frame black Japan/ wood primer/Peelambar check (• or ×)
	7 7 7					3	541	Company of the Compan	A Company of		(C)	AT LACTOR			ζ.	X		Windows lentil & sill level (✓ or 🗙)
							•	a) Table				9	۴	1	%	((Windows size (✓ or 🗙)
					(QUI della manara di	2.2		ζ.	\	ζ	\	<	Windows - template depth & diagonal (✓ or 🗙)
)							((?	۲	<	Windows - template powder coated (✓ or 🗙)
				5	400	1	1		1				eg miles	CO Character	7	į		Loft & Kitchen platform required? (Yes or No)
					?			i		4)		F10-14	7	<u>)</u>	Loft & Kitchen platform provided (✓ or X or NA)
111111111111111111111111111111111111111				1		`)	,)	j		1	An agricult)	V		Loft & Kitchen platform