Quality Control Check Repot. Stage: After Plastering (Apartments)

Flat No.	A-101	Other		SI. No.	32 700
Company	Sor(UP)	Project	SOV	Phase	₹)
Prepared by	S. Kulderp	Sign	Supple	Date	21/01/19
Project Manager	3	Sign	X	Date	21/01/19
Previous stage report no.	10.	32454	Report filed and signed by PM?	d by PM?	Yes No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	commendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making Proceed with further work. ATR not required	port to QC team. Proce er submitting ATR on ing corrections pointed red.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required Proceed with further work. ATR not required.	y QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark v for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering).
- Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have ½"grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.