## Quality Control Check Repot. Stage: After Plastering (Apartments)

Flat No.  Company  Prepared by	Sor (UP) Project	Other Project Sign	105	SI. No.  Phase  Date	32595
Prepared by	S. Kulder	Sign	-Buldus-	Date	08/01/19
Project Manager	K. Pushotham	Sign	<b>\</b> €	Date	08/01/19
Previous stage report no.	no.	71428	Report filed and signed by PM?	d by PM?	☑Yes ☐No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work. Proceed with furth	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after rechect Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report Proceed with further work. ATR not required.	eport to QC team. Proceed ter submitting ATR on ting corrections pointed ired.	ecommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	k by QC. .m. t. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

## Notes:

- Mark  $\vee$  for correct or minor mistake which does not require correction Mark  $\times$  for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have ½"grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Rer	15	14	<u></u>	12	=	10	9	8	7	6	Ų,	4	, ω	2	-	S No
Remarks	Other	Other	Kitchen	Utility/balcony 3	Utility/balcony 2	Utility/balcony-l	Lebby 1	Dining	Brawing-	Feilet-3	Bedroom 3 calin	Toilet 2 0.5-2	Bedroom 2 w.s-1	Toilet 1 twild	Bedroom lauption	Room
			1	1	1	1	1	١	1	!	(	ζ,	<	<	٢	Skirting Provision
			t	1	1	١	1	)	1	1	(	ı	1	1	7	Finishing around door frame ( v or x)
			i	1	1	1	,	) <sub> </sub>	1	Ī	1	7	ς	(	(	Beams & columns finishing ( > or ×)
			!	1	ı	1	)	1	}	?	١	1	1	1	1	Finishing of lofts ( v or x)
			1	1	1	!	1	I	1	1	\	۲	١	ς	,	Electrical junctions finishing ( > or ×)
			1	1	1	1	1	1	1	1	(	7	1	7	1	Window check <sup>6</sup> ( v or x)
			1	1	1	1	1	1	1	1	1	1	1	7	1	Tiles provision ( v or x)
			1	!	1		1	j	1	)	1	]	)	1	1	Sink provision & size (✓ or ×)
			i		1	1	1		1	!	7	ţ	'	٢	7	Grooves for door frames ( v or x)
			1	1	1	1	1	,	1	1	1	,	1	1		Balcony & terrace sill top finishing( • or ×)
			,	ı	ı	1	1	١	1	,	L	}	ī	<	1	Screeding in bathroom & utility ( v or x)
			1 1		1	1	1	1	! !	,	1		!			Screeding in 6" above FFL? (✓ or ×)