Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Recommendation: Stop further work. Stop further work. Proceed with further Proceed with further	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
Recommendation: Stop further work. Submit ATR on QC.report to QC team. Proceed only after recheck long Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.		10.	Purshattam	V. Sanket	Sev(11p)	82
o QC team. Pomitting ATR	MD Sign	31484	Sign ·	Sign	Project	Slab No.
Stop further work. Submit ATR on QC.report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR no Proceed with further work. ATR not required.	7. 10.00	Report filed and signed by PM?	X	V.Sak.str	Sov	02
C.	For filling	M?	Date	Date	Phase	Sl. No.
	□Yes □No	√Yes □No	26-09-18	26-09-18	X	31573

Slab Check. Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.
 Prepare Slab Dimensions Check Plan as follows:

 Show outer dimensions of slab. (Tolerance 2")
 Show length and width of balconies (Tolerance 1")
 Show inner dimensions of ducts. (Tolerance 1")
- Show location of sunken slab. Print an A3 size plan.

- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been easted. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Slab Dimensions Check Plan enclosed?	3d?		✓ Yes ☐ No	No	י יייסיונוטדו שאימשו מוווניוואוטון וויעו וו	0.10.
Staircase - mid landing1	Specified ht:	F- 7	Actual ht: L' h	11 / 11	Within tolerance of 1/2"?	✓Yes □No
Staircase - mid landing 2	Specified ht:	1	Actual ht:	١	Within tolerance of 1/2"?	☐Yes ☐No
Staircase width	Specified wd: 6.6 " Actual wd:	6-6"	Actual wd:	6-6"	6'-6" Within tolerance of 1/2"?	Yes No
Staircase slab thickness	Specified:	ייט	5" Actual:	দ্	Within tolerance of 1/4"? Yes \[\] No	Yes No

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting. Quality of centering, rod bending and concreting?	☐ Good ☑ Avg. ☐ Bad
18"extension to beam bottom runners on outer side provided?	☐Yes ▼No
Quality of Bracing Provided?	Good Avg. Bad
Alignment of beams on outer side?	☐Good Avg. ☐ Bad
Shuttering leveling?	Good ☐ Avg. ☐ Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Remarks:	

Slab Steel check. Notes:

- Mark V for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XXX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Remarks:	16. Stee	15. Stee		13. Stee			10. Ste	9. Ste	_						2. Sto	1. St	SNo	The second secon
	Steel check - slab extensions/ joints	Steel check – floating columns	Electrical Conducting	Steel Check - Column steel overlapping length and cranking	Covering blocks for slab	Steel Check - Slab Extra Bars	Steel Check – Slab cranking & chairs	Steel Check - Slab spacing of bars	Steel Check - Slab size of bars	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item	
	١	٦	~	<	<	4	<		~	1	<u> </u>	<	۷.	~	4	_	Quantitative Check (✓ or X)	
- 1	☐Good ☐ Avg. ☐ Bad	Good Avg. Bad	Good Avg. Bad	☐ Good 🗹 Avg. ☐ Bad	Good Avg. Bad	☐ Good ☑ Avg. ☐ Bad	Good Avg. Bad	☐ Good ☑ Avg. ☐ Bad	Good Avg. Bad	Good ☐ Avg. ☐ Bad	☐ Good Avg. ☐ Bad	☐ Good 📈 Avg. ☐ Bad	☑ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	✓ Good ☐ Avg. ☐ Bad	Good Avg. Bad	Qualitative Check (Good / Avg / Bad)	