Fw: 71

From: nilgiriestate@modiproperties.com

To: cr@modiproperties.com

Cc: kprasad@modiproperties.com

Date: Saturday, February 4, 2017, 06:49 PM GMT+5:30

Sir,

Please find the attachments,


Regards, Mallikarjun.

---- Forwarded Message -----


From: Nilgiri Estates <nilgiriestate@modiproperties.com>


To: Nilgiri <nilgiriestate@modiproperties.com> **Sent:** Saturday, 4 February 2017 6:13 PM


Subject: 71




nash Area polasting points to shift from son to east side. Fappoint > Additional tap point required a lan Area.	
Changes in kitchen platform: (mark on plan) Changes will be intimated later	
Buyers sign: Engg. Sign: Date Page 3 of 4	:: 14/04/16











Site Office: Sy. No. 100/2, Rampally, Keesara Hyderabad- 501 301 Ph: +91-92470 73975

Owned & Developed by: NILGIRI ESTATES



71

Head Office: 5-4-187/3&4, II Floor, M.G. Road, Secunderabad - 500 003 Phone: +91-40-66335551 Email: info@mod properties.com www.modiproperties.com

Details of Additions & Alterations

Villa No	71	Туре	Deluxe / Semi-Deluxe
Buyer Name	CH. SRIRAN	1A SASTA	
Phone No.	9030111945	Email	Sysastry (@ gonail.com

I hereby confirm that I have given the details of the minor additions and alterations that are required in the above referred villa in the pages attached herein. Please complete the changes suggested by me. I agree to pay the charges, if any, for the additions and alterations that I have asked you to make, as per the rates suggested by you. I shall deliver all the materials that are required to be provided by me at the site on or before . In case I fail to deliver these items to the site by the specified date. you may complete the works in the villa as per the standard items provided by you.

Buyers sign	+ railuy	Engg. Sign	NAS.
Date:	14/4/16	Date	14/04/16


Note:

- 1. Colour shades of paints may vary from batch to batch & company to company. The Builder will not take responsibility of quality of work for dark shades especially green & blue
- 2. Shade / colour of natural material like marble and granite can't be guaranteed and may vary from lot to lot. Cracks like appearance in marble is a natural feature and Builder shall not be responsible for repairs or replacement.
- 3. Availability of bathroom or flooring tiles of the same type /colour/make can not be guaranteed and closest possible type/colour/make may be used in its place.
- 4. No further change shall be permitted from this day.
- Please sign on all pages.

Buyers sign:

Page 1 of 4

Date: 14/04/16



Kitchen platsom to be provided on single part.	11
which can be compounded by Earl side part.	A
Wich can be compensated by East side pro-	
and the second	
" C 1 water heater: (h)	
Details of solar water heater: Lefficed.	
in and me for windows,	1-11
Other Changes: Mosquito mesh once for windows, (Hallkoutside) doors at Steps, Hooks at haller parking area, Shifting of commod's to back side, area, Shifting of commod's to back side,	
(Hall Rows state) higher parking	
doors at steps Hours	
alitting of commods to back Side,	
area, sure of wall), Shifting of	4
extension of mall (stifling of wall), Shifting of	
Le yeary door in master bedroom.	
path room see alimning area above nath &	ride Window.
bath room door in master bedroom. Lott roof required a dinning area above nath &	
0 = 1	
Buyers sign: Engg. Sign: Wth Date	0:14/04/16
Ruvers sign: Engg. Sign: Date	:19(04)
Page 4 of 4	