Remarks from site on the 'Requisition by Site Report' of purchase division

Company:		Aedis Developers LLP			Date:		21-05-2022			
Site:		MGA			Prepared by:		Pushpalatha			
			05-2022 to 20-05-2022			Approved by:		Sarwar		
			5-2022							
List of requisitions numbers missing in the report:										
List of requisitions where PO/WO not prepared 3 working days after requisition:										
Req No. Req Da					m Description			Reason for not preparing PO/WO#		
100599 1		0597	1		Wardrobe		PO n	PO not Issue		
List of requisitions where PO/WO is prepared and items have not been received at site beyond the lead time:										
Req No.		Date	Serial no of item in Req.	1	Item Description		Details of discussion with supplier ^s			
100599 06-0		5-2022	-2022 1-3		2 model plates, 5 amps sockets		Material is ready at SSLLP, Will get within three working days.			
			-			10,		D		
						0 1				
				r i						
			,	of .						
No. of gate p	asses issu	ed this w	reek:			From No.	-	ToN	No	
Delivery van site visit on: 13th 15th 18th 21st										
Inward repor	t (MRN/o	ther) & s	stock report emailed in pdf fe			ormat to purchase?		Yes / No		
Items not ordered but received:										
Other corrections & remarks:										
Details of steel & cement stock										
Sl. No	. No Tor size		Wt per mtr kgs	Wt. for 12 mt rod – kgs		Stock at site no of rods		Stock at site in Kgs	Previous stock in Kgs	
1.	8mm		.395		4.74	C a				
2.	10mm		.617	7	7.404					
3.	12mm	-	.89	1	0.68					
4.	16mm		1.58	1	8.96					
5.	20mm		2.47		29.64					
6.	25mm		3.86	- 4	6.32					
7.	32mm		6.32	7	75.84	2				
8.	Binding	wire	7				7 7			
OPC stock			OPC last weeks stock			PPC/PSC stock		PPC/PSC last weeks stock		
Details			Project Manager			Admin Of	ficer/N	Manager	Admin Audit	
Sign						Lustpalata				
Date		1:	21-05-2022		21-05-2022					
Notes: 1. * Send a	copy of the	missing re	quisitions to Purcha	se immediately.	2. Sen	d this report to	purchase	modiproperties.	com, ashaiya@modiproperties.com and	

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to purchase@modiproperties.com, ashaiva@modiproperties.com and raikumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without ompleting this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis.

5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. Suggested remarks - Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under labrication, WO - material for labrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier paragraphs of the responsibility of engineers at site – purchase to write 'NA' in reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report within officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!

Page 1 of 1