Remarks from site on the 'Requisition by Site Report' of purchase division

Company: Aedis			is Developers LLP			:		03-09-2022				
Site: MGA			4			ared by:	Pushpalatha					
Report From / To 27-08-			-2022 to 02-09-2022			roved by:	Sarwar					
Report Date		03-08-2	-2022									
List of requisi	tions nu	nbers m	issing in the rep	ort:								
List of requisi	tions wh	ere PO/	WO not prepared	3 working	days	after requisit	ion	:				
Req No. Req Date			Serial no of	Item	em Description			Reason for not preparing PO/WO#				
•			item in Req.									
List of requis	itions wh	ere PO/	WO is prepared a	and items ha	ve no	t been receiv	ed a	at site beyond	the le	ead time:		
Req No.			Serial no of item in Req.	o of Item D		escription		Details of discussion with suppliers				
NIL												
								T	NI-			
No. of gate passes issued this			week: Nil			From No.		- 10	No.	-		
Delivery van	site visit	on:		27th 29th	01ª 0	2 ^{na}						
Inward repor	t (MRN/c	other) &	stock report ema	stock report emailed in pdf format to purch)	Yes / No				
Items not ord												
Other correct	ions & re	marks:										
Details of ste			<								1 '- 1/-	
Sl. No	Tor size		Wt per mtr	Wt. for 12	mtr	Stock at site		Stock at site i	n	Previous stock in Kgs		
J. 1.0			kgs	rod – kgs		- no of rods	S	Kgs				
1.	8mm		.395		4.74		-					
2.	10mm		.617		.404		-					
3.	12mm		.89		0.68		-		-		-	
4.	16mm		1.58		8.96		+					
5.	20mm		2.47		9.64		-		-			
6.	25mm		3.86		6.32		+		-			
7.	32mm		6.32	7	5.84		\rightarrow		-			
8.	Binding	wire				DDC/DCC	+		pp	C/PSC last		
OPC stock			OPC last			PPC/PSC		-		weeks stock		
			weeks stock		stock		COL	er/Manager		Admin Audit		
Details			Project Manager			Admin Officer/Manager			710	Admin Addit		
Sign						03-09-2022						
Date			03-09-2022			this report to <u>purchase@modiproperties.com</u> , <u>ashaiya@modiproperties.com</u> and e site without ompleting this report. 4. Ensure that inward numbers are written on						
Notes: 1. * Send	a copy of the	ne missing	requisitions to ruicha	Caraball not	leave th	e site without on	nplet	ing this report. 4. E	nsure t	that inward numb	ers are written on	

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to purchase@modiproperties.com, ashaiya@modiproperties.com and rajkumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without ompleting this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis.

5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8 Suggested remarks - Ready with supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!

Page 1 of 1