## Remarks from site on the 'Requisition by Site Report' of purchase division

Company:		Aedis Developers LLP			Date:			24-09-2022		
		MGA	i <b>A</b>			Prepared by:		Pushpalatha		
		17-09-2	-2022 to 23-09-2022		Approved by:			Sarwar		
Report Date 24-08-			-2022			1.				
List of requisitions numbers missing in the report:										
List of requisitions where PO/WO not prepared 3 working days after requisition:										
Req No.	No. Req Date		Serial no of item in Req.	Item Descr				Reason for not preparing PO/WO#		
List of requisitions where PO/WO is prepared and items have not been received at site beyond the lead time:										
Req No. Req Date		Date	Serial no of item in Req.	Item	Item Description		Details of discussion with supplier <sup>s</sup>			
100607	02-08-2022		1 Securi		ty guard alert		Delay with supplier			
100609	13-09-2022		1-9 CP i		fittings		Partly received from the SSLLP.			
	-									
			6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1							
A 1										
No. of gate passes issued this week:				Nil				- To N	No	
Delivery van			17 <sup>th</sup> 19 <sup>th</sup> 20 <sup>th</sup> 22 <sup>rt</sup>							
Inward report (MRN/other) & stock report emailed in pdf format to purchase?  Yes / No								Yes / No		
Items not ord										
Other corrections & remarks:										
Details of steel & cement stock										
Sl. No	Tor size		Wt per mtr kgs	Wt. for 12 rod – kgs				Stock at site in	Previous stock in Kgs	
1.	8mm		.395	100 1155	4.74	110 01 10	us	Kgs		
2.	10mm		.617		7.404		_			
3.	12mm		.89		10.68		_			
4.	16mm		1.58		18.96					
5.	20mm	11	2.47		29.64			- 1		
6.	25mm		3.86		46.32					
7.	32mm		6.32		75.84					
8.	Binding	wire	·							
OPC stock			OPC last			PPC/PSC			PPC/PSC last	
Details			Weeks stock		stock		OT D.6		weeks stock	
Sign			Project Manager			Admin O		Manager	Admin Audit	
Date			24 00 2022			24.00.0000				
Notes: 1. * Send	a copy of th	ne missing r	requisitions to Purcha	4-09-2022			24-09-2022			
Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to <u>purchase@modiproperties.com</u> , <u>ashaiya@modiproperties.com</u> and <u>purchase@modiproperties.com</u> , <u>ashaiya@modiproperties.com</u> and <u>purchase@modiproperties.com</u> , <u>ashaiya@modiproperties.com</u> , <u>ashaiya@modiproperties.com</u> , ashaiya@modiproperties.com										

Notes: 1. \* Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to <a href="mailto:purchase@modiproperties.com">purchase@modiproperties.com</a>, ashaiya@modiproperties.com and rajkumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without ompleting this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis.

5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$ Suggested remarks – Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daity page for follow up in DO NOT CALL PURCHASE!

Page 1 of 1

D GOLAM SARWAR Project Managar/BRGV