Remarks from site on the 'Requisition by Site Report' of purchase division

Company:		Aedis Developers LLP			Date:		22-10-2022				
		MGA			Prepared by:		Pushpalatha				
		-2022 to 21-10-2022		Approved by:			Sarwar				
Report Date 22-10-											
List of requisi	tions nu	nbers mi	issing in the repo	ort:		17					
List of requisi	tions wh	ere PO/\	WO not prepared	3 working o	days a	fter requis	ition:				
Req No.	Req Date		Serial no of item in Req.	Item Descr		iption		Reason fo	r not	preparing PO/WO#	
100615	100615 18-10-2022		1-5	CP fittings			PO	not issue			
				1:1		haan maadi	wad a	et site hevend	the le	ead time:	
			WO is prepared and items have not been rece				Details of discussion with supplier ^s				
Req No.	o. Req Date		Serial no of item in Req.	Item Description		Details of discussion with supplier					
100607	02-08-2022		1	Security guard alert siren		Delay with supplier					
								y			
							7 4				
	-							3 4 5 5 6 B			
No. of gate passes issued this week:				Nil				- To	No.	-	
Delivery van site visit on:				15 th 17 th 19 th 20 th							
Inward report	(MRN/	other) &	stock report ema	iled in pdf fo	ormat	to purchas	e?			Yes / No	
Items not ord			:		i II. i ii.						
Other correct							4.1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	-		
Details of stee	el & cen	ent stock		10 11 11	74			-		n	
Sl. No	Tor size		Wt per mtr kgs	Wt. for 12 t rod – kgs		Stock at si – no of roo		Stock at site in Kgs		Previous stock in Kgs	
1.	8mm		.395		4.74	g. 10. %					
2.	10mm		.617		.404	St. July St.	. 4				
3.	12mm		.89		0.68	1 2		1			
4.	16mm		1.58	1	8.96	77 1/2	- 12	1			
5.	20mm		2.47		9.64		, '				
6.	25mm		3.86		6.32	2 1					
7.	32mm		6.32	7	5.84						
8.	Bindin	g wire									
OPC stock			OPC last weeks stock	1 10		PPC/PSC stock	?			PC/PSC last eeks stock	
Details		Project Manager					fficer/Manager		dmin Audit		
Sign											
Date			22-10-2022			22-10-2022					
Notes: 1. * Send	a copy of t	he missing	requisitions to Purcha	se immediately.	2. Send	this report to	purch	nase@modiproper	ties.con	n, ashaiya@modiproperties.com and	

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to purchase@modiproperties.com, ashall.not.eave-the-site withis report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis.

5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. Suggested remarks - Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for tabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!

APERCUED BY

APERC

Page 1 of 1