## Internal memo no. 903/35/A Annexure - B RMC pour report

						rayic pour	тероп							
Con	npany/ firm	: MHPL												
Proj	ect:	SOV					Block No.: Su			np walls purpose				
Supplier:			Cemex Infra				Flat / Villa no.:			mp walls purpose				
	uisition nos		185208				Slab no.:							
PO nos.:			88640				A. Estimated quantity:							
Sign of Security							B. Requisition quantity:			6				
		Sign of	Sign of Admin		Sign of Project Manger		C. Actual quantity poured D. Difference (C-A)		17 19					
Details of RMC pour 15 JUN 2022														
Sl. No	Date	Time of disp from RMC plant	Time of receipt at site	Time of Pour	RSOUTHMAN (Sever Oak Villag Part-III) POUTEd	Dc No. / Batch no.	Specified wt @2400 kgs/m3	Measur weigh (kgs)	in we	ight	Deduction for shortfall in Rs.	7 day cube test strength in kN/m2	28 day cube te strengt in kN/n	
1.	08.06.22	12:05	12:38	12:45	8.5	465	20,400	20,660	2			III KIV/IIIZ	III KIN/II	
2.	08.06.22	02:15	14:37	14:45	06	466	12,000	12,050		_				
3.	08.06.22	03:45	16:05	16:15	2.5	468	6000	6,300						
4.							0000	0,300						
5.						· · · · · · · · · · · · · · · · · · ·							-	
6.														
7.						- ;								
8.							<del></del>						-	
9.						7	<del>,</del>						-	
10.														
Total:					17 Cumts		38,400 Kgs	39,010 I	Zgs					
Remarks									0					

Note: 1. Report to be sent on a daily basis to <u>purchasora modiproperties.com</u> and <u>report-auditamodiproperties.com</u>. 2. Report must be prepared during pour and not later. 3. Report must be sent within one working day. 4. Multiple report can be sent for one PO. 5. Weigh all vehicles. 6. 6. cubic meters vehicle should have a net weight of 14,110 kgs @ 2,400kgs/m3. If the shortfall is more than 50 kgs per load purchase to debit supplier shortfall amount on pro-rata basis. 7. Site to calculate shortfall. 8. Maintain original report + weighment slips + pour reports + test reports + photographs at site.