



TAX INVOICE

Cell : 9849102251

M. SUDARSHAN

FABRICATION OF ALUMINIUM PARTITIONS, DOORS, WINDOWS & INTERIOR WORKS

D.No. 1348, Pioneer Bazar, Bollaram, Secunderabad - 500 010. T.S.

Email : sudarshan.maheshwaram@yahoo.com

GSTIN No. 36BBIPM8347N1ZW

Name :

Silver oak villas LLP

5-4-187/384 II Floor Miy Road Secbad

GST No 36 ADBFS 3288 A227

Bill No. 239

Date :

D.C No. 58

Date :

Order No 20230704062 Date : 13-7-2023

Sl No	PARTICULARS	HSN CODE	FOR SIZE	QTY	FOR SFT	Amount Rs.	Ps.
	<u>UPVC windows</u>						
1	1200 x 1200 x 2 nos Fixed	3916		SFT 32-0	315=00	10080	00
2	600 x 1200 x 4 nos o/w	4		32-0	485=00	15520	00
3	1800 x 1200 x 6 nos S/W	"		144-0	335=00	48240	00
4	900 x 1050 x 1 NO S/W	4		10-5	385=00	4042	50
5	600 x 600 x 3 nos battu	3916		12-0	520=00	6240	00

VNO 176

Rupees in Words : Ninety Nine thousand

Two hundred and

Sixty Five only

SUB TOTAL				84122	50
SGST	%	9		7571	025
CGST	%	9		7571	025
IGST	%			1	45
GRAND TOTAL				99265	00

TERMS & CONDITIONS :

1. Goods once sold will not be taken back and No claim for shortage or damage will be entertained.
2. Cheque disonour Rs. 500/- Extra
2. Our responsibility ceases no seener goods are handed over to the carrying agency
4. Subject to secunderabad Jurisdiction Only.

For **M. SUDARSHAN**

Sudarshan

Signature

INSTALLATION REPORT

Company/ firm:	SOV LLP	Requisition nos.:	20230704040
Project:	SOV-TU	PO no.:	20230704062
Supplier:	Misudashan	Material type:	UPVC windows

Details of installation:

Sl. No.	Date of installation	Unit no.	Material details	Size	Qty
1.	12/7/23	126	UPVC sliding with mesh	3'x3.5'	1 no
2.	"	"	"	6'x4'	6 nos
3.	"	"	UPVC openable	2'x4'	4 nos
4.	"	"	ventilator top hung	2'x2'	3 nos
5.	"	"	UPVC fixed	4'x4'	2 nos
6.					
7.					
8.					
9.					
10.					
11.					
12.					
13.					
14.					
15.					

Remarks: Installation done. please approve

Total: 16 nos

Approved by	APPROVED BY Project manager	Security	Admin (Audit)
	18 JUL 2023		

Note: 1. Report to be sent on completion of work. 2. For partial completion report must be sent once a month. 3. This report is required for installation of windows, doors, windows, balcony, staircase railing, fire doors and such materials where PO for material + labour is issued. Exclude false ceiling, painting, water proofing where 'Advice for giving credit to contractor/supplier firm' is being set to R&D. 4. One or more reports can be made per PO. Avoid multiple Pos in one report. 5. Provide report on defaults, poor quality, missing items, etc. 6. Reports to be provided regularly. However, must be provided within one working day of request from purchase.