

Office of the
Director General
Telangana State Disaster Response
& Fire Services, Hyderabad.

Rc.No. 15009/MSB/CR/RR/2013

Dated: -08-2023

MEMORANDUM

Sub:- Telangana State Disaster Response and Fire Services Department – MSB Section – To ensure certain parameters with regard to Fire Vehicle Driveway and turning radius for conducting firefighting and rescue operations – Instructions issued on 02-08-2023 to be kept in abeyance until further orders – Orders Issued - Reg

- Ref:-
1. G.O.Ms. No. 168 MA & UD Department, dt: 07-04-2012.
 2. This office Circular Memo. Rc. No. 15009/MSB/CR/RR/2013, Dt: 16-12-2019.
 3. This office Circular Memo. Rc. No. 15009/MSB/CR/RR/2013, Dt: 02-08-2023.
 4. Representation dated: 18-08-2023 of the President, CREDAI, Hyderabad.

In continuation of the instructions issued vide, reference (3) cited and in view of the discussions held with the senior officers on representations received from CREDAI, Hyderabad vide reference (4) cited, it is informed that, the instructions issued vide reference (3) cited to ensure certain parameters with regard to Fire Vehicle Driveway and turning radius for conducting firefighting and rescue operations during fire and other emergencies in highrise buildings is kept in abeyance until further orders.

- 2). In view of the above, all the inspecting officers are instructed to comply the above instructions and take necessary action accordingly.
- 3). The receipt of memorandum should be acknowledged.


Director General

2/6

Telangana State Disaster Response
and Fire Services & Hyderabad.

To

The Regional Fire Officer, Central Region, Hyderabad.

All the District Fire Officers.

Copy to the Assistant District Fire Officers.

Copy to the Station Fire Officers.

Copy to upload on the website of Telangana State Fire Department.