Remarks from site on the 'Requisition by Site Report' of purchase division

Company:	GV	'RC	Date:			23.09.2023		
Site: Innopoli		opolis	Prepared b	Prepared by:		N.Sai Shivani		
Report From / To 16.09.2023 to 22.09.2023			Approved by:		Mr.Madhu			
Report Date 23.09.2023				•				
List of requisiti	ons number	s missing in the repor	t		•			
List of requisiti	ons where I	PO/WO not prepared	3 working days after	requisition:				
Req No. Req Date S.no			Item Descr	Reason for not preparing PO/WO#				
				1			1 1 5	
20230821033	21-08-202	23 1 to 6	Windows-A1 framing structural Glazing,DGU,SGU,A1 Openable-,cement boards,ACP.		Po not issue.			
20230821034	21-08-202	23 1 to 2	Windows-A1 Framing Structural Glazing,ACP.		Po not issue.			
20230821035	21-08-202	23 1 to3	ACP-0.2+3+0.25mm,Glass Door,Canopy Work.		Po not issue.			
20230902004	02-09-202	23 1 to 2	CIF-power&shine multipurpose cleaner,CIF- Abrasive surface cleaner cream.		Po not issue.			
List of requisiti	ons where I	PO/WO is prepared ar	d items have not been	n received at sit	e beyond	the lead	1 time:	
Req No.	Req Dat		Item Description		Details of discussion with supplier ^{\$}			
20230612015	12.06.202	3 1	FRD do	ors	Exp	pected o	lelivery after 1 week.	
202308170	17-08-202	23 1	CP-Urinal	pan-without		Deli	very after 1 week.	
07			sensor.	-			•	
202308300	30-08-202	23 1	Dortable toil	et cohin	Evn	acted d	alivary ofter 1 week	
11	30-08-20	23	Portable toilet cabin		Expected delivery after 1 week.			
202309120 05	12-09-202	23 1 to 2	Empty papers		Expected delivery on Wednesday.			
202309140 43	14-09-202	23 1	CCTV Ca	CCTV Cameras -PTZ IP		Advice payment		
202309160 07	16-09-202	23 1	Concrete ta	Concrete tapes.		Expected delivery on Tuesday.		
202309150 08	15-09-202	23 1	Flexible copper cable 1.5sqmm-2core.		Expected delivery on Wednesday.			
202309150 13	15-09-202	23 1	Flexible copper cable 2.5 sqmm-12 core.		Expected delivery on Wednesday.			
202309150 14	15-09-202	23 1to2	Contractor, Timmer		Delivery on Monday.			
202309200 20	20-09-202	23 1	Starter Single phase		Delivery on Monday.			
202309210 30	21-09-202	23 1	Cutting Blades		Expected delivery on Tuesday.			
No. of gate pass		nis week:		rom No.	8232	To No.	8234	
Delivery van si			16.09.2023 to 22.09.2					
Inward report (MRN/other) & stock report email	ed in pdf format to pu	ırchase?			Yes	

Items not ordered but received:											
Other corrections & remarks:											
Details of steel & cement stock											
Sl. No	Tor size	Wt per mtr	Wt. for 12 mtr	Stock at site	Stock at site in	Previous stock in Kgs					
		kgs	rod – kgs	– no of rods	Kgs						
1.	8mm	.395	4.74	210	1000	2000					
2.	10mm	.617	7.404	135	1000	1000					
3.	12mm	.89	10.68	0	0	3000					
4.	16mm	1.58	18.96	369	7000	15000					
5.	20mm	2.47	29.64	236	7000	12000					
6.	25mm	3.86	46.32	86	4000	5000					
7.	32mm	6.32	75.84	197	15000	16000					
8.	Binding wire			-	0	100					
OPC stock	Nil	OPC last	Nil	PPC/PSC	539	PPC/PSC last 480					
		weeks stock		stock		weeks stock					
Details		Project Manager		Admin Officer/Manager		Admin Audit					
Sign		T.Madhu		N.Sai Shivani							
Date		23.09.2023		23.09.2023							

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to purchase@modiproperties.com, ashaiya@modiproperties.com and raikumam@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without ompleting this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$Suggested remarks – Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!