## Remarks from site on the 'Requisition by Site Report' of purchase division

Campan	***	Cilve	0.1	, , , , ,	asitioi	n by Site Report' of	purchase divi	sion		
Company: Silv Site; Silv		Silver	ver Oak Villas LLP ver Oak Villas part-III		Date:		18-03-2023			
Report From / To 10		Γο 10-03	Cak Villas pa	art-III			B.Meenakshi Goud			
Керогет	(Fr		3-2023 to 18- 0 sat)	-03-2023	Approved by:		K Purshotham			
Report I	)ate		03-2023							
List of re	onisitio	ons numbe	rs missing in	th.						
List of re	equisitio	ons where	PO/WO not p	tne report':	NILL	ng days after requis				
Req	No.	Req Date	Serial no	repared 3 w	vorkir	ng days after requis	sition:			
neq no. neq			item in R	OI I	Item Description		Reason for not preparing PO/WO#			
List of re	equisitio	ons where I	20/W0 is pro	nared and it						
Req	No.	Req Date	Serial no	of	tems	nave not been rece	ived at site be	yond the lead time:		
1104 1101			item in Re	O	Item Description			Details of discussion with		
212101		21-02-23	1-2		Floor Tiles Kajaria Williams grey & Olimpia Benge		supplier <sup>\$</sup> Material Available Delivery by			
				gr						
2121	36	28-02-23	1-7	CP And	CP Angle cock 15 nos pending		Monday  Material not Available at ssllp			
2121	39	06-03-23	1							
			_			MC-M25	Work under progress			
212146		10-03-23 11-03-23				loor frames	Supplier arranging for material			
				Bras	ss Ball	l cock material	Material delivery by monday			
212149		11-03-23	1-13	45	_	e 63mm 5 nos ending	Material Delivery by today			
212153		13-03-23	1	Ta		r rough stone	evening  Material delivery by next week			
212154		13-03-23	1		-	cks-12 balance	Material not Available at ssllp			
212155		14-03-23	1			1C-M25	Work under progress			
20230315026		15-03-23	1-5		UPVC	windows	Supplier arranging for material			
20230315052		15-03-23	1-4	Z	angle	e templates	Supplier arranging for material			
2023031 53		15-03-23	1-4			e templates	Supplier arranging for material			
20230315054		15-03-23	1-4		Z angle templates			Supplier arranging for material		
20230316029		16-03-23	1-5		UPVC windows					
lo. of gate passes issued t					2/5 From No.		Supplier arranging for material			
		visit on: 3d		11-03-23	3 (Sati		4121	Го No. 4122		
	an site (	visit oii. su	ays	18-03-23	3 (Satu	rday), 13-03-23(MC	onday), 15-03-2	23(wednesday) and		
ıward rep	ort (M)	RN/other)	& stock repo	rt emailed i	n pdf	format to		Yes		
urchase?					•			163		
		but receiv								
		& remarks								
	teel & c	ement sto	ck							
. No	ttt	7	Wt per mtr.	Wt. for 12		Stock at site -	Stock at	Previous stock in		
		ļ.	kgs	mtr rod –	kgs	no of rods	site in Kgs	Kgs		
1. 8mm			.395	4	4.74	507	2400			
2. 10mm		n	.617	7.	404	433	3200	-		
	3. 12mm		.89	10	0.68	96	1020	_		
	12mn		1.58		3.96	96 33 625		-		
	12mn	ı	1.50		29.64		-			
3.			2.47		9.64	-				
3. 4.	16mm	ı		29	9.64 5.32	-	-	-		

8.	Binding wire	-		Nill	Nill	Nill	
C stock	Nill	OPC last weeks stock	Nill	PPC/PSC stock	332	PPC/PSC last weeks stock	297
etails gn ate		Project Manager 18-03-2023		Admin Officer/N	Admin Officer/Manager		

Notes: 1. \* Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to <a href="mailto:purchase@modiproperties.com">purchase@modiproperties.com</a>, and <a href="mailto:raikumarn@modiproperties.com">raikumarn@modiproperties.com</a> on every Saturday. 3. Admin offices shall not leave the site without completing this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DC's / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MD's approval/input, 8. \$ Suggested remarks – Ready with supplier, Supplier not contacted/, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!