Remarks from site on the 'Requisition by Site Person of Control of the State Person of Control of Co

		311	e on the 'Regu	isiti	on bar dia					
Compan	y: Si	ilver Oak Villas pa	ert-III	151(1	on by Site Re	eport' of	purchase	divis	ion	
		Iver Oak Will		Date:			26-06-20			
REDUIT		21 10 /0 06 21/2		Pr	Prepared by:		B.Meenakshi			
Report Date 26		5-06-2021	r(in to sat)	Ap	proved by:		K Purshotham			
List of re	quisitions numbe	ers missing in the	'enort*							
List of red	quisitions where	PO/WO not prepa	red 2							
Req N	o. Req Da	te Serial no	of Working	g day	ays after requisition:					
		item in Re	eq	Item Description		Reason for not preparing PO/WO#) #	
List of req	uisitions where I	PO/WO is prepare	d a 1							
Reg No	Req Dat	e Serial no c	d and items ha	nd items have not been recei			ite beyond	the	lead time:	
		Item in Ro	item in Req.		cription	Details of discussion with supplier ^s				
183563	30-03-202	1 1 to 5		WPC door frames7'X3'						
			WPC doc			Stock Not available at 3			at SSLLP.	
No. of gate	Nil / 5	_	Б эт				2711			
Delivery va	nn site visit on:1			26.0	From No.	om No. Nill 21,25.06.21,23.06		No.	Nill	
Inward repo	ort (MRN/other)	& stock report en	nailed in pdf fo	20.U	06.21,25.06.2	1,23.06	.21		X7 / XT -	
Hellis not of	dered but receiv	cu.	20.06.21,26 tock report emailed in pdf form			to purchase?		Yes / No		
Other correc	ctions & remarks	3:								
Details of st	teel & cement sto	ock								
Sl. No	Tor size	Wt per mtr	Wt. for 12 m	. 4	G. 1			- 1 · 77		77
		kgs	rod – kgs	ıır	Stock at sit			n	Previous stock in Kgs	
1.	8mm	.395	4.7		- no of rod		Kgs			
2.	10mm	.617	7.404		_	_	-			
3.	12mm	.89	10.63		_	_	-			
4.	16mm	1.58	18.		_					
5.	20mm	2.47	29.	_	_	-			· · · · · · · · · · · · · · · · · · ·	
6.	25mm	3.86	46				-			
7.	32mm	6.32	75.:		_					
8.	Binding wire	-		-	Nill	Nill			Nill	
PC stock	Nill	OPC last	Nill		PPC/PSC	303		DD	C/PSC last 245	
		weeks stock			stock	505		1	eks stock	
etails		Project Manager			Admin Officer/Manager			Admin Audit		
ign					Meanaly			710	min Audit	
at a		No.			91000					

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to purchase@modiproperties.com, ashaiya@modiproperties.com and rajkumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without ompleting this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$ Suggested remarks - Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!

26-06-2021

26-06-2021