**DELIVERY CHALLAN** 

**©**: 8367679193

## SAI VISHAL ENTERPRISES FLY ASH BRICKS

Factory: Godumakunta Vill., Keesara Mdl, Medchal Dist.

Office: Street No. 17, Tarnaka, Secunderabad.

	GSTIN: 36ACZPL151	12H17F	· /
No.	021	Date	7-06.24
M/s	Cres Centra	Calso M	r GA
P.O.	No 200 1007 01 00	Date :	
S.No.	PARTICULARS	BRICK SIZE	QUANTITY
)	Endred Poury	GX8X16	50 My
	V-W: 1508 UE	WORK-	ED 190818000
	9 193 Inwa	2 P 31:04 b	Dt:17 6 24  Ot: Sign
	own: Churchy CF	RESCENTIAL	BS PVT LTD
	A Company of the Comp	Jory	50 M
	rived the above material For sod condition	SRI SAI VISHA	L ENTERPRISES
Rec	eiver's Signature	4	7

## Internal memo no. 903/35/A Annexure -D Cement Blocks – Weekly Delivery Report

				•	
Company/ firm:	Crescentia labs pvt ltd   Requisition nos.	Requisition nos.:	20240326033	Total PO quantity:	2250
Project:	Gvone	PO No.	20240326051	Quantity delivered in earlier period:	2200
Block /Flat / Villa no.:	Towards compound wall brick work	Total material delivered Yes/ No	Yes/ No	Quantity delivered during week:	50
Supplier:	Sri sai vishal enterprises   Close PO:	Close PO:	Yes / No	Balance quantity to be delivered:	
Sign of security		Sign of Admin		Sign of Project manager	18-06-2024
Date	18-06-2024	Date	18-06-2024	Date	

Details of solid blocks – delivered in earlier period.

S No	Date	Time	Block Size & type	Quantity delivered	DC No.	Inward no.	MRN No.
1							
	Total:						

Details of solid blocks – delivered during the week.

S No	Date	Time	Block Size & type Quantity delivered	Quantity delivered	DC No.	Inward no.	MRN No.
1	17-06-24	18:00	6"x8"x16"	50	021	1695	20240618005
<u>3</u>							
	Total:			50			
Remark	Remarks: Po to be closed			-			

Note: 1. Report to be emailed to <u>purchase@modiproperties.com</u> and <u>report-audit@modiproperties.com</u> every Saturday. 2. Maintain original along with delivery challans along with photos at site. 3. Report must have totals calculated. 4. Specify block size and block type (solid / hollow). 5. Total quantity and delivered quantity includes all types of blocks. 6. One running report must be made per PO.