EHS Audit - Site Visit Report

Company		MRM LLP	Audited by	B.Lokesh		
Site		GMR	8ign	B.Kell		
Project manager name		N.Sripivas Ahmed	Date	24.06.24	24.06.24	
Sign		(6)m	Previous site visit date	16.05.24		
be visited AGH may	by Lokesh atleast once a	week and this report to be sent.	 This report to be sent on site viber All other sites may be visited once it ood, avg., poor. In ATR required fil 	two weeks. 5. Sites	like Serene and	
Sl. No.	Description/com	pliance with safety pro-	cedures	Rating		
1.	Labour complian	Avg				
2.	Tying of safety r	Good				
3.	Material stored s	Good				
4.	Engineers aware	Good				
5.	Maintenance of I	Avg				
6.	Electrical power	Avg				
7.	Working of guare	Good				
8.	Working of came	Avg				
9.	Maintenance of c	Good				
10.	Safety procedure	Avg				
S No.	Suggested rectific	ATR required				
1.	Some of the labo imposed fine.	ATRIEquired				
2.	Electrical DB box					
3.		,				
l. No.	Suggested improv					
1.		V	are cashiy taken up)			
2.						
3.						
il. No.	Suggested improv Admin/Construct					
1.		The Litery				
2.						
3.						

EHS Audit – Site Visit Report

Company		Crescentia Labs	Audited by	B Lokesh kumar		
Site		G V 1	Sign	T. John		
Project manager name		S V Subha reddy	Date	27-06-2024		
Sign		· Live	Previous site visit date	06-06-2024		
AGH may must send	be visited once in a month/ ATR within 3 days of this i	quarter. 6. Rating should be good report.	This report to be sent on site viber all other sites may be visited once in l, avg., poor. 7. In ATR required fil	group on same day. 3 n two weeks. 5. Sites I Yes/No. 8. Project r	B. All major sites to like Serene and nanager/Engineer	
Sl. No.	The state of the s		res		Rating	
1.	Labour compliance with PPE				Avg	
2.	Tying of safety nets wherever required.				Poor	
3.	Material stored sat	Good				
4.	Engineers awarene	Avg				
5.	Maintenance of labour quarters, cleanliness, provision of toilets & water supply.				Avg	
6.	Electrical power si	Good				
7.	Working of guard	Avg				
8.	Working of camera	Avg				
9.	Maintenance of cre	Good				
10.	Safety procedures	Good				
S No.	Suggested rectification	ATR required				
1.	Some of labour are					
2.	2 Engineers are not wearing shoe impose fine on them, as per circular					
3.	Remove safety nets all sides, tie new nets,80% Nets are damaged					
Sl. No.	Suggested improvements in SOP (that can be easily taken up)					
1. 2.						
3.						
Sl. No.	Suggested improve Admin/Constructio					
1.						
2.						
3.						

Lol 2 ×16/2024