



31/3/22.

Make shaded
drawing.

Left tank fitting in utility.




31/3/22

① Road facing planter b/w driveway & retaining wall on road. Fill - mosses up to 750mm below retaining wall. excavate & plant tacoma plants - 4 slightly potted.

② Shift crabs to H. block lower beds. Dismantle old sales office



③ Deduct 50% in Manner for VDF




h

31/7/22

8/4/22.




South coyneal ~~with~~ wall plat.




recon- 33'
plat
+ Gulcher
@ 15'

22/4

32'6"




22/4 left floor.



8 par lf.



One beam grade.

↓ 1/4" par.




15 par lf.

22/4/22


A blow fast East side
stilt from plank.


12/5

B 4 D black.




12/5






2 nos 35w L&D. (6 dia & 6 pin).


27/5/22



2 nos


3' 9mm







on shade grows

7005 on tail





29/5Slab joint for drive wayStep

Use NIUBOND with
6" paint ~~brush~~ ^{brush}



17/6




2.5 m
2 m
1 m


1.2 m
1.5 m



22/7

RWHS for 20m East road.





Gravite.





26/8

16 mm for steel.

26/8

150 mm long x 8 mm
Bombay nail.


100 mm
 chain.

29/9

Dir 6' - 6'8"

Pituch tank for vain water.

Structure of pile bed.

Make 2 pile
tanks.

7 layer each

at 2 places.


PVC tree guard mesh.

below ~~HDPE~~ Agro mesh.

HDPE Green agro mesh


1 year layer.



— total 4 layer.



5mm hole at

both of pipe





21/15/22

House keeping

3

A block — 1 M/c + 1 opuch + 1 sweep.

B block — ↓ ↓ ↓
 Shar Shar + 1 Sweep

AAB block — 1 Manual M/c + 1 Sweep.
 Stilt floor



Amphitheatre — 1 Manual M/c + 1 Sweep.
 + Benches

Perimeter — 1 Manual M/c + 1 Sweep.
 Road & Seabank

Total 1 M/c opuch.
 25 Sweeps.


All on A/c of association!

6/11/22




Same gate design as A/B blat

↑
adjust to fit.



2.
 $\frac{24}{11} \parallel 24$




Each of neutral - each should be
 3m from each other.

75x6m $\rightarrow$ Inter cannot ~~each~~ all each.

75x6m " " all neutral.
2

6/11/22



During


Site

Date:

Location

4/22 Early ocean A block by - (south)


10 in sq. rod @ 5'





All pr @ 1.5 in

11/11/22

8m pipe length: — x 75mm — support
~~between~~ between H & E block.










2921

90 x 90 Coler

7/1/23


40 mm pipe for garden






66
+ 14
+ 20
(90)

7/1/23 CRILWAT NEST





4" Mown
4" OLC
4" RLC



26/1/23



100 mm MS pipe for SW drain.






20/1/23


Pallet - tray



10/2/23



10/3 footpath splay



20/2/23

① → Inspect following apartment flat to check whether
 Stage-I - A block completed,
 to check whether stage-I works were
 completed, main door is locked, flat is
 cleaned, there no material lying in flat.

Block A - 5 flats

" B - 8 "

" C - 13 "

" D - 12 "


" G - 13 "

" E - 8 "

② → Send mail to Sivadas with list of
 flat for inspection on 1-Mar-2023 for
 each default ₹ 500 fine imposed per flat
 per default on consent engineer.

3/8/23


Club house cafe. — open comb. L — sign.



3/5/23


Ratio between R & D blocks


East side:



8/8/23

Western pedestrian walk way
 along C 4 E Blvd.






8 rows of 16m with stumps @ 150m




12/5/23

Reinforced Column support to driveway slab
near clubhouse.





8 rods of 16mm.

lock set upto 100mm is
floor & ceiling.





11/7/23

OUTER PART OF D BLOW.




4/8




4/8Handicap ~~area~~ area,

6m green



18m green!

4/8

1200 x 2400 ft area given
 0.5m given area

25/8

Cable tray plan.




cables to be laid nearby with.

6 to 12 mm spacing & cable size @


mm.

Second or third layer can be laid
as above if required.





625mm



10mm rod.

25/08/23

club house 1st floor:-

- 1) 3+1+1x2 sets fabric sofa + 2 coffee tables in main lounge
- 2) 10 more chairs for banquet hall.
- 3) large gas stove - 2 no's
- 4) gas cylinder - 1 no's
- 5) Heavy duty exhaust fan - 1 no in kitchen

●

2nd floor coffee:-

- 1) place kitchen cabinets on ~~western~~ eastern wall of pantry. Mix and match stock available ss/sslp.
- 2) overhead cabinet to south east wall. of pantry / based on availability. ^{be placed}
- 3) paint entire coffee ^{walls} with sand's or time - 42022 colour.
- 4) order 1 pool table, 1 tt table, 1 foos ball table, 2 carrom boards with stands, 3 no's of ton's ac, 43" ind tv, Sony play station, 12 tables of 30"x48" with ss stand.
- 5) 60 chairs novella, Nilkamal/beige
- 6) ~~2 door~~ order 12 no's hanging lights for open area coffee & 2 fans
- 7) Complete ceiling plaster with putty/pop.

@reach

- 1) order same items as GHT
- 2) required pants platforms ⁱⁿ with granite.
- 3) First aid room ordered all items as per circular

4) society office

- 1) society office is used as sales office / st
- 2) store room used as sales conference
- 3)
- 1) badminton court complete flooring with loose vitrified tiles
- 2) place order badminton court + mats + mats with ramesh.

Library Yoga room

- 1) Order Sony music system
- 2) rosewood low storage
- 3) order 8 yosamats
- 4) east & north wall colour orange tanrok-113
- 5) west & south wall off white

Gym

- 1) All walls ~~warm stone~~ silver grey 0015
- 2) Order 2 treadmills, 2 multi gym, 2 elliptical trainers, 1 rolling machine, 1 exercise cycle and all items marked in point no-10 of Im 9/2/13u/b/f to x

Library open & lounge

- 1) 10' bar same as repl in the middle of south wall with bar stool - UNO's order 12 nos garden
- 2) pottigo chairs / same as sov model villa / Wense colour shift & round coffee table from sov model villa on G.T.
- 2) fix 3 8 watt lights ~~be~~ stool

library

off white




- Order 2nd book shelf / natural wood colour (MD)
- 2) order 2nd 3 seater faux leather sofa's,
 - 3) order 2nd 6 seater dining table however with 4 chairs.
 - 4) book shelf as same mpl.
 - 5) All walls warm stone ONO2

open & lounge

- 3) wall behind bar texture with Burnished earth-14
- 4) eastern wall warm sandstone ONO2
- 5) other walls off white



- small 2, big ss birds.
- 1) in 6 ss bird in each tail & Hair dryer
 - 2)

25/8/20



25/r

Beam and wall joint joint






25/8/23

Rate for E block roof joists.

- ① Rod banded — R. 6/- per kg.
- ② Century — R. 8 per ~~sq~~ sft (side only).
- ③ CC panning — R. 1.00 per cum.

✓

1/9/23

4521

15/9/23

ATR is pending

- 1) G-207, 42051 - ATR is pending
- 2) driveway 42299 - ATR is pending
- 3) C-305, 40075 - ATR is pending
- 3) C-501, 42076 -
- 4) G-405, 42086
- 5) G-501, 42087
- 6) F-106 42112
- 7) G-103 42112
- 8) G-104 42123
- 9) G-109 42176
- 10) C-301 42218
- 12) G-607 42219
- 13) G-302 42224
- 14) G-504 42256

Re check

- | | |
|----------------------------|------------------|
| 1) G-407, 42059 - Re check | |
| 2) G-301 42085 | 16) G-407, 42171 |
| 3) F-303 42115 | 28) F-603 42265 |
| 4) F-304 42116 | 17) G-503 42178 |
| 5) F-305 42117 | 29) F-606 42266 |
| 6) G-303 42124 | 18) G-607 42179 |
| 7) G-305 42125 | 30) |
| 8) G-403 42058 | 19) G-202 42180 |
| 9) H-305 42311 | 20) G-204 42181 |
| 10) H-306 42310 | 21) G-406 42194 |
| 11) G-401 42126 | 22) F-501 42195 |
| 12) F-404 42123 | 23) F-502 42198 |
| 13) F-405 42133 | 24) F-506 42200 |
| 14) F-404 42134 | 25) G-401 42216 |
| 15) G-303 42137 | 26) C-101 42217 |
| | 27) G-307 42218 |
| | 28) F-601 42263 |
| | 29) F-602 42264 |

ATR is pending

15/9/23

- 1) G-207, 42051 - ATR is pending
- 2) driveway 42299 - ATR is pending
- 3) C-305, 40075 - ATR is pending
- 3) C-501, 42076 -
- 4) G-405, 42086
- 5) G-501, 42087
- 6) F-106 42112
- 7) G-103 42112
- 8) G-104 42123
- 9) G-109 42176
- 10) C-301 42218
- 12) G-607 42219
- 13) G-302 42224
- 14) G-504 42256

Ge Recheek

- 1) G-407, 42059 - Ge recheek
- 2) G-301, 42085
- 3) F-303 42115
- 4) F-304 42116
- 5) F-305 42117
- 6) G-303 42124
- 7) G-305 42125
- 8) G-403 42058
- 9) H-305 42311
- 10) H-306 42310
- 11) G-401 42126
- 12) F-404 42123
- 13) F-405 42133
- 14) F-404 42134
- 15) G-303 42137
- 16) G-407, 42171
- 17) G-503 42178
- 18) G-607 42179
- 19) G-802 42180
- 20) G-204 42181
- 21) G-406 42194
- 22) F-501 42195
- 23) F-503 42198
- 24) F-506 42200
- 25) G-401 42216
- 26) C-101 42217
- 27) G-307 42221
- 28) F-601 42263
- 29) F-606 42266
- 30) F-602 42264

Aakash to study following system send report of any defect.
 repair requires
 → wa

~~16/09/23~~ 16/09/23 water supply

19/09/23 water supply sumps & septic tanks


20/09/23 electric power supply + generator backup

21/09/23 Fire fighting system



22/09/23 lifts

23/09/23 common area lighting

- email to be sent to A suresh of GHT to check & report 3 no's each on tuesday and friday's between 4 and 6 pm.
- email of ^{list} flats to be check must be sent to Suresh atleast one day in advance. Suresh to mark original & report with blue pen.
- report to be send shoham on 12pm every Saturday.





15/12/23




22/2



Steel for making seafoldy.



0.5m steel

16/2 laban phi - septa-jah





① 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

Rock cuttings for testing required?

For

10/5

1) ~~Footings~~ S_1 - NO

S_2 - NO

S_3 - NO

S_4 - YES

S_5 - NO

S_6 - NO

S_7 - NO

S_8 - YES

S_9 - YES

S_{10} - YES

S_{11} - YES

$S_{12, 13, 14, 15, 16}$ - NO

S_{13} - NO

S_{14} - NO

S_{15} - NO

S_{16} - NO

1) now Q_1 - YES

Q_2 - YES

Q_{14} - YES

Q_3 - YES

Q_{15} - NO

Q_4 - YES

Q_{16} - NO

Q_5 - YES

Q_6 - YES

Q_7 - YES

Q_8 - YES




Q_9 - YES

Q_{10} - YES

Q_{11} - YES


Q_{12} - YES

Q_{13} - NO




16/8

Speed breaker design.




Remove 600 mm x 50 mm. cc.




16/8

B108 - D105

Beam between



3/8



5/9/29

Today task is

Corr wall. B Block. 9th Paint 44'
of C/wall.

Again paint.


Ex. 3m wrap

External tarp wall

Simultaneously and change.

- ② change ~~stick~~ wall Black.
- ③ change Foot rest (simultaneously)
- ④ paint along road. (gate 3/4)
- ⑤ paper plastic on South & East ^{road} side.
NFC
- ⑥ looks for Not producing as Entry road

5/9/24

Water filter plantWater props.lay 100 mm ce with ~~start~~ $\odot$ 200.Steel grid of 8mm $\odot$ 200 mm.Start with bottom most filter