## EHS Audit - Site Visit Report

Project manager name Srinivas.N/Ahmed Date 26-12-2024    Sign	Company		MRPLLP	Audited by B Lokesh Kun		I	
Note: 1. Original copy of report + ATR to be sent to MD (Ashaiya). 2. This report to be sent on site viber group on same day. 3. All major sites to be visited by Lokesh atleast once a week and this report to be sent. 4. All other sites may be visited once in two weeks. 5. Sites like Serene and AGH may be visited once in more through the sent. All other sites may be visited once in two weeks. 5. Sites like Serene and AGH may be visited to be visited by solve. 8. Pro	Site			Sign	Lokesh		
Note: 1. Original copy of report + ATR to be sent to MD (Ashaiya). 2. This report to be sent on site viber group on same day. 3. All major sites to be visited by Lokesh atleast once a week and this report to be sent. 4. All other sites may be visited once in two weeks. 5. Sites like Serene and AGH may be visited once in a month/quarter. 6. Rating should be good, avg., poor. 7. In ATR required fill Yes/No. 8. Project manager/Engineer must send ATR within 3 days of this report.  SI. No. Description/compliance with safety procedures  Rating  1. Labour compliance with PPE Good  2. Tying of safety nets wherever required.  3. Material stored safely and properly.  4. Engineers awareness and compliance with safety procedures including their PPE. Avg  5. Maintenance of labour quarters, cleanliness, provision of toilets & water supply. Good  6. Electrical power supply for construction activity, pumps, temporary lighting. Avg  7. Working of guard siren.  8. Working of cameras + power supply to cameras.  9. Maintenance of creche, creche teacher, mid-day meals.  10. Safety procedures for earth work including earth storage, barricading, shoring. Good  S No. Suggested rectifications/corrections  1. Safety nets need to maintain properly,  2. Cleaning required in multiple areas  3. SI. No. Suggested improvements in SOP (that can be easily taken up)  1. 2. 3.  SI. No. Suggested improvements in SOP (to be implemented after discussion with MD/ Admin/Construction Team/Etc.)	Project	manager name	. <b>\</b>	Date	26-12-2024		
be visited by Lokesh atleast once a week and this report to be sent. 4. All other sites may be visited once in two weeks. 5. Sites like screne and ACH may be visited once in a month/quarter 6. Rating should be good, avg., poor. 7. In ATR required fill Yes/No. 8. Project manager/Engineer must send ATR within 3 days of this report.  SI. No. Description/compliance with safety procedures  1. Labour compliance with PPE Good  2. Tying of safety nets wherever required. Good  3. Material stored safely and properly. Good  4. Engineers awareness and compliance with safety procedures including their PPE. Avg  5. Maintenance of labour quarters, cleanliness, provision of toilets & water supply. Good  6. Electrical power supply for construction activity, pumps, temporary lighting. Avg  7. Working of guard siren. Good  8. Working of cameras + power supply to cameras. Avg  9. Maintenance of creche, creche teacher, mid-day meals. Avg  10. Safety procedures for earth work including earth storage, barricading, shoring. Good  S No. Suggested rectifications/corrections ATR requ  1. Safety nets need to maintain properly,  2. Cleaning required in multiple areas  3. SI. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)  1.							
1. Labour compliance with PPE  2. Tying of safety nets wherever required. 3. Material stored safely and properly. 4. Engineers awareness and compliance with safety procedures including their PPE. Avg  5. Maintenance of labour quarters, cleanliness, provision of toilets & water supply. Good  6. Electrical power supply for construction activity, pumps, temporary lighting. Avg  7. Working of guard siren. Good  8. Working of cameras + power supply to cameras. Avg  9. Maintenance of creche, creche teacher, mid-day meals. Avg  10. Safety procedures for earth work including earth storage, barricading, shoring. Good  S No. Suggested rectifications/corrections ATR requ  1. Safety nets need to maintain properly,  2. Cleaning required in multiple areas  3.  Sl. No. Suggested improvements in SOP (that can be easily taken up)  1.  2.  3.  Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)	be visited AGH may	by Lokesh atleast once a way be visited once in a month.  ATR within 3 days of this	eek and this report to be sent. 4. A /quarter. 6. Rating should be good report.	ll other sites may be visited once in a vg., poor. 7. In ATR required fill	two weeks. 5. Sites	like Serene and	
2. Tying of safety nets wherever required.  3. Material stored safely and properly.  4. Engineers awareness and compliance with safety procedures including their PPE. Avg  5. Maintenance of labour quarters, cleanliness, provision of toilets & water supply. Good  6. Electrical power supply for construction activity, pumps, temporary lighting. Avg  7. Working of guard siren. Good  8. Working of cameras + power supply to cameras. Avg  9. Maintenance of creche, creche teacher, mid-day meals. Avg  10. Safety procedures for earth work including earth storage, barricading, shoring. Good  S No. Suggested rectifications/corrections ATR requ  1. Safety nets need to maintain properly,  2. Cleaning required in multiple areas  3. SI. No. Suggested improvements in SOP (that can be easily taken up)  1. 2. 3. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)	Sl. No.					Rating	
3. Material stored safely and properly.  4. Engineers awareness and compliance with safety procedures including their PPE. Avg  5. Maintenance of labour quarters, cleanliness, provision of toilets & water supply. Good  6. Electrical power supply for construction activity, pumps, temporary lighting. Avg  7. Working of guard siren. Good  8. Working of cameras + power supply to cameras. Avg  9. Maintenance of creche, creche teacher, mid-day meals. Avg  10. Safety procedures for earth work including earth storage, barricading, shoring. Good  S No. Suggested rectifications/corrections ATR requ  1. Safety nets need to maintain properly,  2. Cleaning required in multiple areas  3. SI. No. Suggested improvements in SOP (that can be easily taken up)  1. 2. 3. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)	1.	Labour complianc	Good				
4. Engineers awareness and compliance with safety procedures including their PPE. Avg  5. Maintenance of labour quarters, cleanliness, provision of toilets & water supply. Good  6. Electrical power supply for construction activity, pumps, temporary lighting. Avg  7. Working of guard siren. Good  8. Working of cameras + power supply to cameras. Avg  9. Maintenance of creche, creche teacher, mid-day meals. Avg  10. Safety procedures for earth work including earth storage, barricading, shoring. Good  S No. Suggested rectifications/corrections ATR requ  1. Safety nets need to maintain properly,  2. Cleaning required in multiple areas  3. Sl. No. Suggested improvements in SOP (that can be easily taken up)  1. 2. 3. Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)	2.	Tying of safety ne	Good				
5. Maintenance of labour quarters, cleanliness, provision of toilets & water supply.  6. Electrical power supply for construction activity, pumps, temporary lighting.  7. Working of guard siren.  8. Working of cameras + power supply to cameras.  9. Maintenance of creche, creche teacher, mid-day meals.  10. Safety procedures for earth work including earth storage, barricading, shoring.  Good  S No. Suggested rectifications/corrections  ATR requ  1. Safety nets need to maintain properly,  2. Cleaning required in multiple areas  3.  Sl. No. Suggested improvements in SOP (that can be easily taken up)  1.  2.  3.  Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)  1.	3.	Material stored sat	Good				
6. Electrical power supply for construction activity, pumps, temporary lighting. 7. Working of guard siren. 6. Good 7. Working of guard siren. 6. Good 8. Working of cameras + power supply to cameras. 9. Maintenance of creche, creche teacher, mid-day meals. 10. Safety procedures for earth work including earth storage, barricading, shoring. 11. Safety nets need to maintain properly, 12. Cleaning required in multiple areas 13. Sl. No. Suggested improvements in SOP (that can be easily taken up) 14. 2. 3. 15. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.) 1. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)	4.	Engineers awarene	Avg				
7. Working of guard siren.  8. Working of cameras + power supply to cameras.  9. Maintenance of creche, creche teacher, mid-day meals.  10. Safety procedures for earth work including earth storage, barricading, shoring.  Good  S No. Suggested rectifications/corrections  1. Safety nets need to maintain properly,  2. Cleaning required in multiple areas  3. Sl. No. Suggested improvements in SOP (that can be easily taken up)  1. 2. 3.  Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)	5.	Maintenance of labour quarters, cleanliness, provision of toilets & water supply.				Good	
8. Working of cameras + power supply to cameras.  9. Maintenance of creche, creche teacher, mid-day meals.  10. Safety procedures for earth work including earth storage, barricading, shoring.  Good  S No. Suggested rectifications/corrections  1. Safety nets need to maintain properly,  2. Cleaning required in multiple areas  3. Sl. No. Suggested improvements in SOP (that can be easily taken up)  1. 2. 3.  Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)	6.	Electrical power su	Avg				
9. Maintenance of creche, creche teacher, mid-day meals.  10. Safety procedures for earth work including earth storage, barricading, shoring.  S No. Suggested rectifications/corrections  1. Safety nets need to maintain properly,  2. Cleaning required in multiple areas  3. SI. No. Suggested improvements in SOP (that can be easily taken up)  1. 2. 3. SI. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)	7.		Good				
10. Safety procedures for earth work including earth storage, barricading, shoring.  S No. Suggested rectifications/corrections  ATR requipments a safety nets need to maintain properly,  Cleaning required in multiple areas  SI. No. Suggested improvements in SOP (that can be easily taken up)  1. 2. 3.  SI. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)	8.	Working of camera	Avg				
S No. Suggested rectifications/corrections  1. Safety nets need to maintain properly, 2. Cleaning required in multiple areas 3. Sl. No. Suggested improvements in SOP (that can be easily taken up) 1. 2. 3. Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)	9.	Maintenance of cre	Avg				
1. Safety nets need to maintain properly, 2. Cleaning required in multiple areas 3. Sl. No. Suggested improvements in SOP (that can be easily taken up) 1. 2. 3. Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.) 1.	10.	Safety procedures f	Good				
2. Cleaning required in multiple areas 3. Sl. No. Suggested improvements in SOP (that can be easily taken up) 1. 2. 3. Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.) 1.	S No.	Suggested rectifications/corrections ATR required					
3. Sl. No. Suggested improvements in SOP (that can be easily taken up)  1. 2. 3. Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)  1.	1.	Safety nets need to					
Sl. No. Suggested improvements in SOP (that can be easily taken up)  1. 2. 3. Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)  1.	2.	Cleaning required i					
1. 2. 3. Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/ Admin/Construction Team/Etc.)  1.	3.						
2. 3. Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/ Admin/Construction Team/Etc.)  1.	Sl. No.	Suggested improve	ments in SOP (that can b	e easily taken up)			
3.  Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)  1.							
Sl. No. Suggested improvements in SOP (to be implemented after discussion with MD/Admin/Construction Team/Etc.)  1.							
Admin/Construction Team/Etc.)							
		Suggested improver Admin/Construction	ments in SOP (to be imp n Team/Etc.)	lemented after discussion	with MD/		
2.							
	2.						
3.	3.						

## EHS Audit - Site Visit Report

Company		MRPLLP	Audited by	B Lokesh Kun	mhr .
Site		NGH	Sign	Bloke	uh.
Project manager name		Vijay faj	Date	27-12-2024	
Sign			Previous site visit	date 20-12-2024	
AGH may must send	be visited once in a mor ATR within 3 days of the	nth/quarter. 6. Rating shoul his report.	sharya) 2. This report to be sent on site sent. 4. All other sites may be visited of d be good, avg., poor 7. In ATR requir	NAMED OF TAXABLE PROPERTY OF TAXABLE	Lilan Canana A
SI. No.	Description/con	Rating			
1.	Labour complia	Avg			
2.	Tying of safety	Avg			
3.	Material stored	Avg			
4.	Engineers aware	Avg			
5.	Maintenance of	Good			
6.	Electrical power	Good			
7.	Working of guar	Good			
8.	Working of cam	Good			
9.	Maintenance of	Good			
10.	Safety procedure	Good			
S No.	Suggested rectif	ATR required			
1.	Cleaning require	· · · · · · · · · · · · · · · · · · ·			
2.					
3.					
Sl. No.	Suggested impro				
1.			, ,		
2.					
3.					
Sl. No.	Suggested impro				
1.					
2.					
3.					