EHS Audit - Site Visit Report

Company		MRPLLP Audited by B LOKESH		B LOKESH			
Site		GMR	Sign	TI band	and		
Project manager name		АНМЕР	Date	67-04-2025	07-04-2025		
Sign		Mune ?	Previous site visit date 20-03-2025				
AGH may must send	be visited once in a mo ATR within 3 days of the	onth/quarter. 6. Rating should be his report.	a). 2. This report to be sent on site. 4. All other sites may be visited good, avg., poor. 7. In ATR requi	e viber group on same day. Sonce in two weeks. 5. Sites red fill Yes/No. 8. Project re	3. All major sites to like Serene and nanager/Engineer		
Sl. No.	Description/cor	Rating					
1.	Labour complia	Avg					
2.	Tying of safety	Good					
3.	Material stored	Good					
4.	Engineers awar	Good					
5.	Maintenance of	Good					
6.	Electrical power	Good					
7.	Working of gua	Good					
8.	Working of car	Good					
9.	Maintenance of	Good					
10.	Safety procedu	Good					
S No.	Suggested recti	ATR required					
1.	Labour quarters						
2.	Finishing stage PPE labour need to maintain compulsory						
3.							
SI. No.	Suggested improvements in SOP (that can be easily taken up)						
1.							
2.							
3.				: ::1.100/			
Sl. No.	Suggested impro Admin/Constru						
1.	The second second		1 - 4 - 10 / 10 - 10 - 10 - 10 - 10 - 10 - 10				
2.							
3.							

EHS Audit - Site Visit Report

Company		NGH	Audited by	INVA		
Site		NGH	Sign Sign	B LOKESH		
Project manager name		Vijay raj	Date	- Telakon	The later of	
Sign			And the second s	08-04-2025 to 04-03-2025		
must send	ATR within 3 days of ti	nm quarter. 6. Rating shou	shaiya). 2. This report to be sent on site v sent. 4. All other sites may be visited or ld be good, avg., poor. 7. In ATR require	ober group on vame day	S. All major sites to like Service and nanager Engineer	
Sl. No.	Description/cor	Rating				
1.	Labour complia	Avg				
2.	Tying of safety	Good				
3.	Material stored	Good				
4.	Engineers awar	Good				
5.	Maintenance of	Good				
6.	Electrical power	Good				
7.	Working of gua	Avg				
8.	Working of car	Good				
9.	Maintenance of	Good				
10.	Safety procedu	Good				
S No.	Suggested recti	ATR requires				
1.	PPE Need to fol					
2.	Labour quarters	The same of the sa				
3.	Water State of the Control of the Co					
SI. No.	Suggested impr					
2.						
3.		THE RELIES OF THE PARTY OF THE				
SI. No.	Suggested impr Admin/Constru					
1.						
2.						
3.						