Construction Division - Material Requirement - Site Report

| Company: Mehta & LLP | | a &Modi Realty Ko | wkur Date: | | 30-08-2025 | | |
|---|------------------------------|--|---|---|--|---------------------------------------|--|
| Site: GHT | | | Prepar | ed by: | N.Subhash | | |
| | | 8.2025 TO 29-08-20 | 25 Appro | ved by: | A.Suresh | | |
| Report Date 23.08.20 | | 8.2025 | | | | | |
| ist of items th | at require SK | U: | | | | | |
| | | O/WO not prepared | after 3 working da | ays of requisition | n: | | |
| Req No. | Req Date | | Item Description | | Coordinate with purchase /procurement and give reason for delay. | | |
| 0250711009 | 11-07-202 | | Water level indicators& Hub Rack | | Online Purchase. | | |
| ist of requisit | ions where P | O/WO is prepared a | nd items have not | been received a | t site beyond the lea | d time: | |
| PO No. PO Date | | Serial no of item in PO. | Item Descri | iption D | Details of discussion with supplier & expected date of delivery | | |
| 20250828010 | 28-08-25 | The same of the sa | Eco drain pi | pes-6'' | Thursday to be Received. | | |
| 20250825024 | 25-08-25 | A STATE OF THE PARTY OF THE PAR | Balcony Glass | | Work is in Progress. | | |
| 20250825025 | 25-08-25 | CONTRACTOR OF THE PARTY OF THE | UPVC Windows | | Work is in Progress. | | |
| 20250825028 | 25-08-25 | THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER. | Panel do | Management of the Park of the | Monday to be Received. | | |
| 20250825030 | 25-08-25 | | Malasian Bro | wn Tiles | Monday to be Received. | | |
| 20250820053 | 20-08-2 | THE RESERVE AND ADDRESS OF THE PARTY OF THE | PPC Cen | | Monday to be Received. | | |
| 20250722003 | 22-07-202 | NAME AND ADDRESS OF THE OWNER, WHEN PERSON AND PARTY OF THE OWNER, | Oscar & Rang Tiles | er Blue | Expected delivery on Next week. | | |
| 20250605020 | 05-6-202 | 1 | Glass balcony stainless steel- 900Hmm | | Work is in Progress. | | |
| No. of gate pa Delivery van Items not ord | site visit on:2 | 28-08-2025 | I | From No. | To No. | | |
| DOs to be see | ered but recei | erial not required /in- | correctly made: | | | | |
| A | rened - man | material received - N | ARN not unloaded | 1. | | | |
| Approved PC | od part mat | erial received – furtl | ner material not re | equired/will be o | rdered by new requi | sition: | |
| Other correct | iona & romar | be- | ici materiai not re | dan our min or o | | | |
| Details of ste | ol & coment | ntools | | | | | |
| Sl. No | Tor size | Wt per mtr kgs | Wt. for 12 mtr rod – kgs | Stock at site - no of rods | Stock at site in tons | Previous weeks stock in tons | Stock as per M-codex in Kgs |
| 1. | 8mm | .395 | 4.74 | | 0.00 | 0.00 | 0.0 |
| | 10mm | .617 | 7.404 | | | 0.00 | 0.0 |
| 2 | - | .89 | 10.68 | | | 0.00 | 0.0 |
| 2. | 1 2111111 | | 10.06 | 0.00 | 0.00 | 0.00 | 0.0 |
| 3. | 12mm 16mm | 1.58 | 18.96 | | | | |
| 3. | 16mm | 1.58 2.47 | 29.64 | 0.00 | | 0.00 | The second secon |
| 3. 4. 5. | 16mm 20mm | | 29.64 46.32 | 0.00 | 0.00 | 0.00 | 0.0 |
| 3. 4. 5. | 16mm | 2.47 | 29.64 | 0.00 0.00 0.00 | 0.00 | 0.00 | 0.0 |
| 3. 4. 5. 6. 7. | 16mm 20mm 25mm 32mm | 2.47 3.86 6.32 | 29.64 46.32 | 0.00 0.00 0.00 0.00 | 0.00 0.00 0.00 | 0.00 0.00 0.00 | 0.0 |
| 3. 4. 5. 6. | 16mm 20mm 25mm | 2.47 3.86 6.32 | 29.64 46.32 | 0.00 0.00 0.00 0.00 PPC/PSC stock | 0.00 0.00 0.00 P | 0.00 | 0.0 |
| 3. 4. 5. 6. 7. 8. OPC stock | 16mm 20mm 25mm 32mm | 2.47 3.86 6.32 re - OPC last weeks stock | 29.64 46.32 | 0.00 0.00 0.00 0.00 PPC/PSC | 0.00 0.00 0.00 P | 0.00 0.00 0.00 PC/PSC last | 0.0 |
| 3. 4. 5. 6. 7. 8. | 16mm 20mm 25mm 32mm | 2.47 3.86 6.32 re - OPC last | 29.64 46.32 | 0.00 0.00 0.00 0.00 PPC/PSC stock | 0.00 0.00 0.00 P | 0.00 0.00 0.00 PC/PSC last | The second secon |

purchase@modiproperties.com, janaki@modiproperties.com and audit@modiproperties.com on every Saturday.

Intl memo no. 912-73-B - Material requirement site report 21-6-25 ver11.doc

Page 1 of 2