
Compan	ıy Name:	Silver Oak Villas LLP				Annear	i	ļ	************************************
Project:		Silver Oak Villas		************	<u> </u>	Approved	oy:	ļ	
Work Description:		Swimming Pool rock cutting		***************	<u> </u>	Sign:	\$ ************************************	***************************************	[] }
Contractor Name		V.Mallaiah		*********		<u> </u>	<u>-</u> 		
Prepared By		K.Purshotham		*******	ļ	i 6	*************************		***************
Date:	14 h/294 (74) 4044 244 244 244 244 244 244 244 244 24	03.11.18		**************					*********************
	***************************************	***************************************	***************************************	***************	·····	***************************************			**************************
S No.	Item Head	Item Description	Length	Width	Height	Nos.	Quantity	Units	Item Head Tota
1	club house	rock cutting	2.00	2.00	6.50	1.00	26.00	Cft	******************************
	**************************************	***************************************	2.00	2.00	6.50	1.00	26.00	Cft	**************************
ĺ	******************************	****	2.00	2.00	6.50	1.00	26.00	Cft	##344 \#66##4 PA.B4\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	# C35a bbb van f4403+8640 qby444444444444		2.00	2.00	6.50	1.00	26.00	Cft	*****************************
	***************************************	**************************************	2.00	2.00	6.50	1.00	26.00	Cft	
	**********************	49.04 (40-444)-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-	2.00	2.00	6.50	1.00	26.00	Cft	
	***************************************	***************************************	2.00	2.00	6.50	1.00	26.00	Cft	***********************
j			2.00	2.00	6.50	1.00	26.00	Cft	************************
		The second secon	2.00	2.00	6.50	1.00	26.00	Cfi	*************
			2.00	1.50	6.50	1.00	19.50	Cft	******************************
	74F1347-1-347-1-3-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-		2.00	2.00	6.50	1.00	26.00	Cft	*************************************
	**************************************		1.00	1.50	5.50	1.00	8.25	Cn	
	*******************************		2.00	2.00	5.50	1.00	22.00	Cft	
			2.00	2.00	3.50	1.00	14.00	Cft	anadoritriya itaziyi iraqdadadadanınlışın
	nd kana nikakakakakakakakaka na cad - ar s jama		2.00	2.00	3.50	1.00	14.00	Cft	
	******		2.00	2.00	3.00	1.00	12.00	Cft	*****************************
	148-80.460\$0)81-84184011weak1191194484		2.00	2.00	3.00	1.00	12.00	Cft	***************************************
	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		2.00	2.00	3.50	1.00	14.00	Cft	>#### 1 heart passes
	******************		2.00	2.00	4.00	1.00	16.00	Cft	
	lviveencing>mdiinpequaneadamhmiye\pecs		2.00	2.00	4.00	1.00	16.00	Cft	7-7-4-6-4-6-4-6-4-4-4-4-4-4-4-4-4-4-4-4-
	. 648827 progressor - 22 64 644 644 644 644 644 644 644 644 6		2.00	2.00	4.00	1.00	16.00	Cft	********************************
	 		2.00	2.00	4.00	1.00	16.00	Cft	#49#mai\\
	**************************************		2.00	2.00	3.83	1.00	15.32	Cft	
			2.00	2.00	3.83	1.00	15.32	Cft	**
		***************************************	2.00	2.00	3.83	1.00	15.32	Cfl	. 7000) 64-6476-791-423-63-9996-745-649
			2.00	2.00	3.83	1.00	15.32	Cft	4,,bd,42; P4,2,-4);#84134,444,444,44;
	441 J		2.00	2.00	3.83	1.00	15.32	Cft	44-3vnavastitiis.\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
2 1	Loose Boulder cutting near club house for Lifting		6.00	4.00	3.83	1.00	91.92	Cft	\\max\\\max\\max\\max\\max\\max\\max\\m
	h4<40>>Abdroor.occ<80.144.hqq,40;+40;+4030	***************************************	4.66	3.00	2.50	1.00	34.95	Cft	
	*****************************	10 Compression and the contract of the contrac	5.00	5.00	1.50	1.00	37.50	Cft	to de transport de la completa del la completa de la completa del la completa de la completa del la completa de la completa de la completa del la completa de la completa del la c
	**					TOTAL		***************************************	680.72



Ę. , sohammodi@modiproperties.com

From: srinivas kuchimanchi <ksri707@gmail.com>

Cc: Purshotham - Engineer <purshotham@modiproperties.com>

Dear Sir,

be followed by us at any point of time. that this kind of mistakes will not be repeated, your rules and regulations will room concrete by mistake thinking QC was done, it is my assurance to you I apologize for the mistake happened at villa number 79, we have done head

K Srinivas Thanks®ards SR Builders