

sohammodi@modiproperties.com

From: purshotham@modiproperties.com
Sent: 01 10 2018 1:15 PM
To: sohammodi@modiproperties.com
Subject: Fw: Reg:-Error in V.no 73 1No footing position is misplaced by 2'.
Attachments: WhatsApp Image 2018-09-28 at 10.05.38 AM (1).jpeg; WhatsApp Image 2018-09-28 at 10.05.38 AM.jpeg; WhatsApp Image 2018-09-28 at 10.05.41 AM.jpeg; 180928112644.pdf

Soham Sir,

Please advise for the below Error in v.no 73 Footing.

As we have completed all the footings and pedestals of V.no :-74,75,76.

Regards,

K.Purshotham.

From: purshotham@modiproperties.com
Sent: Friday, September 28, 2018 11:45 AM
To: sohammodi@modiproperties.com
Subject: Reg:-Error in V.no 73 1No footing position is misplaced by 2'.

Soham Sir,

Please find the attach V.no 73 Footings photograph & Footing Centre line plan.

This is to inform you that in V.no 73 1No footing position is misplaced by 2'.

this is error is done by Surveyor. when our Site Eng checked pedestals starter before casting the error was found.

The same we have informed to Contractor. Mr Srinivas of KSR Builders . He agreed to break the footing and cast new footing as per drawing.

Please advise,

Shall we go head to break the footing and cast new footing.

Regards,

K Purshotham.
Project Manager | +91 95021 77288 | purshotham@modiproperties.com
Modi Properties Pvt. Ltd. | www.modiproperties.com
5-4-187/ 3 & 4, M G Road, Secunderabad -03 | Ph: +91 40 6633 5551
Don't just buy a flat or villa! Buy a great lifestyle!
We build affordable flats & villas in gated communities.

sohammodi@modiproperties.com

From: ANIL KUMAR REDDY.S <civil.anils@gmail.com>
Sent: 01 10 2018 6.36 PM
To: Soham Modi
Cc: karunakar
Subject: Regarding compressor machine.

Sir,
Compressor machine called by purshotham sir is at site but it was not employed since 5 days

Regards,
S Anil Kumar Reddy
Project Manager
Surasani Constructions Pvt Ltd
8123097211.

--
Regards,
S Anil Kumar Reddy,
Project Manager,
Surasani Constructions Pvt. Ltd
8123097211